LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

L

For	corne	erc in
1 01	CUFFIE	- 1 S III

on this certificate.

Schoolcraft	Located In:	Corner Code #	
(County)		,	655 45.2
1. Public Land Survey	T R T R		H 8
2. Property Controlling in Section	S 12 T 42N R 16W S T R S 12 T 42N R 16W	8 (GCDB 620540)	20 20 24
3. Miscellaneous Property in Sec.	S T R S T R	(GCDB 620520)	
	ecorded Plat		Register of Deeds Stam
5. Private Claims			1 2 6 - 5 - 1

p & File Number

1, Stephan J. Szyszkoski , in a field survey on 09/17/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2, above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 12) Center-West 1/16 corner, Section 12. Not previously monumented.

(11-Sec. 12) Southwest 1/16 corner, Section 12. Not previously monumented.

OF MICH STEPHAN J. SZYSZKOSKI LAND SURVEYOR 33986 ANDS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 12) Established the position for the corner midway and on a straight line between Quarter corner 1337.29' west and the intersection of 1/4 lines of Section 12, 1337.29' east.

(11-Sec. 12) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

10" Cedar S62°E 16.23' mrkd "W1/16 BT" 6" 8" Cedar N53°E 12.48' do 8" 5" Cedar N28°W 19.82' do 8" 8" Cedar S27°W 19.40' do 5"	1) Set 1"IDx28" I.pipe with 2" alum. W.Birch S74°W 11.95' mrkd "3" B.Spruce S07°E 15.21' B.Spruce S23°W 26.48' B.Spruce N04°E 28.78' 8057545.915 N= 140503.388	MDNR cap. SW1/16 BT" do do do
---	--	---

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83 (2011) Datum). Coord. Ref.=NGS PID DL6164: N= 131822.939 m. E= 8059239.498 m.

Signed by	O.S. al		20		
- No your	- Johnson	uol.	_ Date	02/04/2015	
Surveyor's Michigan License No.		33986			

Revised Oct., 1995