

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

SCHOOLCRAFT
(County)

Located in:

Corner Code ##

- | | | |
|------------------------------------|---|-------------|
| 1. Public Land Survey | T <u>42N</u> R <u>17W</u> | <u>J-11</u> |
| | T <u>42N</u> R <u>17W</u> | <u>K-12</u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling In Section | S <u>36</u> T <u>42N</u> R <u>17W</u> | <u>5</u> |
| | S <u>36</u> T <u>42N</u> R <u>17W</u> | <u>6</u> |
| 3. Miscellaneous | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, Gerald L. Wiggins, in a field survey on 11-21 & 11-27, 19 90, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- J-11 North 1/4 Corner of Section 35. OBT'S: 4" Beech, N45°W, 3 lks. & 5" Beech, S38°E, 9 lks.
- K-12 East 1/4 Corner of Section 35. OBT'S: 7" Beech, N40°W, 20 lks. & 12" Beech, S50°E, 30 lks.
- 5 North 1/16 Corner of Section 36. Not previously set.
- 6 N.E. 1/16 Corner of Section 36. Not previously set.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- J-11 Cor. set by bearing and distances shown on Boundary map of Palms-Book State Park as surveyed by Gregory A. Shadko L.S. #1934 in 1940. He set a wood stake at cor. from one original BT A Beech 5" S38°E, 19 lks. No evidence of stake or Beech tree was found.
- K-12 Corner set midpoint on line between N.E. Corner and S.E. Corner of Section 35.
- 5 Cor. set m.p.o.l. between computed center of sec. 36 and North 1/4 Cor. sec. 36 as set by Gregory A. Shadko L.S. # 1934 using his bearing and distance as shown on boundary map of Palms-Book State Park.
- 6 Corner set at intersection of the North 1/16 line sec. 36 and the east 1/16 line sec. 36 as run on a mean bearing between the N-S 1/4 line and the east sec. line of sec. 36.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
DNR MONUMENT SET AT ALL FOUR CORNERS.

- | | |
|---------------------------------|-------------------------------------|
| J-11 10" Y. Birch, N26°W, 13.8' | K-12 14" Clump Maples, N74°E, 43.3' |
| 8" Y. Birch, N20°E, 12.4' | 6" Beech, S68°E, 57.4' |
| 14" Beech, N38°E, 16.2' | 5" Beech, S56°E, 53.45' |
| 6" Beech, S24°E, 36.2' | 4" Maple, S15°W, 4.4' |
- 5 10" Maple, North, 16.3 & 8" Maple, S70°W, 22.3' & 12" Maple, S23°W, 12.25' & 10" Maple, S18°E, 14.15'
- 6 12" Cedar, North, 23.9' & 10" Cedar, N73°W, 29.6' & 10" Cedar, S14°E, 26.1' & 6" Cedar, S27°E, 36.0'

Signed by

Surveyor's Michigan License No.

23521

Date 4-2-90

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

