## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_43\_ NR\_\_14\_ W

	- 2 c n o o i c r a i t COUNT
DESCRIPTION OF CORNE	R Meander corner between Section 12 and 13 on the right bank of Manistique River.
DESCRIPTION OF CORNER	MONUMENT_1" Pipe with 4" Brass Cap
WITNESSES TO CORNER	lo" Cedar (M. C. NBT) N 26° W 70 Links
	15" Hemlock (M, C. NBT) S 88° W 17 Links

**RESTORED.** This corner was replaced from one Cedar B. T. bearing S 65° W 17 Links. Stump in poor condition. Corner found by Forestry Division Survey Crew. Note: Meander Corner lies 2.19 Chains east of Section Corner 11, 12, 13, and 14.

Corner was placed and witnessed February 20, 1958.

SURVEYORS SEAL

SIGNED SILLY D. SUCKLES PEGISTERED LAND SURVEYOR

DATE 2/25/60 \_

Billy D. Buckler