

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
MACKINAC CO. 3 CORNERS.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 44 N. R. 11 W. XX	G-3, G-4
2. PROPERTY CONTROLLING IN SECTION	9, T. 44 S. R. 11 W. XX	7
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-18 & 8-19, 19 87, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-3 Northwest Corner of Section 10. Butler Ives 1849., Tam 7", N44°E, 30 lks. & Tam 9", S37°W 50 lks.

G-4 West 1/4 Corner of Section 10. Butler Ives 1849. Sugar 7", S83°W, 28 lks. & Sugar 8, S87°W, 32 lks.

7 North 1/16 Corner on East side of Section 9.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-3 Corner set by proportionate measure from corners 1/2 mile West, 1 mile East, and 1 mile South. Found Tam. Stumps that fit original BT'S but could not identify as such.

G-4 Corner set midpoint on line between N.W. Corner and S.W. Corner of Section 10.

7 Corner set midpoint on line between N.W Corner and West 1/4 Corner of Section 10.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
DNR Monuments set at all three corners.

G-3 5" Cedar, S32°E, 4.0'	G-4 6" Maple, N73°W, 16.9'	7 6" Maple, S60°E, 16.9'
4" Cedar, N22°W, 12.65'	6" Maple, N32°E, 27.6'	6" Maple, N38°W, 25.4'
8" Cedar, N27°E, 17.0'	6" Maple, N74°E, 11.9'	8" Beech, N5°W, 24.9'
5" Cedar, N77°E, 6.25'	12" Maple, S18°E, 28.6'	5" B.Ash, N85°E, 26.6'

SIGNED BY Gerald L. Wiggins


DATE 2-3-88

SURVEYOR'S MICHIGAN REGISTRATION NO. 23521

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET