

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 13 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 7-8-17-18

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6-15-62

WITNESSES TO CORNER..... 6" Dead Cedar Stump West 13 links



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two cedar stump bottoms at proper bearing and distance.

Found several blazes around corner and blazes along the 1/2 mile to West of Corner.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*

REGISTERED LAND SURVEYOR  
Billy D. Buckler

DATE

4-2-64