

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46N N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section corner 22-23-26-27

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-2-62

WITNESSES TO CORNER..... 8" "ed Pine (S23 NBT) N25°W, 122 links



11" red pine (S22 NBT) N56°E, 46 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by double proportionate measure from corners 1 mile south;  
3 miles west;  $2\frac{1}{2}$  miles north and 2 miles east. No evidence of original corner.

Corner lies  $\frac{3}{4}$  chain S. of ditch.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 19, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler