

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N. R. 15W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 1-12

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/22/64

WITNESSES TO CORNER..... 18" Jackpine ( $\frac{1}{4}$ S NBT) S20°E 12 $\frac{1}{2}$  Lks.



23" W. Pine ( $\frac{1}{4}$ S NBT) N15°W 73 $\frac{1}{2}$  Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from one Y. Pine Stump; a probable Bearing Tree, in proper position.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler  
BILLY D. BUCKLER  
REGISTERED LAND SURVEYOR  
DATE 8/4/1964