

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 NR. 15 W

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 9 and 16

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 1/2" Brass Cap

WITNESSES TO CORNER 10" W. Pine (1/4" NBT) N 75° E 319 Links

7" J. Pine (1/4" NBT) N 60° E 205 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from a 10" W. Pine Stump N 82° E, 2.25 chains
Notch visible, no other marks.

Corner was placed and witnessed July 19, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 7/28/60