

52

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T 46N R 15W M6

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

May 20 1996

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	19	20	21	22	23	24				
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

(M6) Quarter corner common to Sections 13, T46N-R15W and 18, T46N-R14W. Corner reestablished in 1963 by Billy D. Buckler, RLS, "by single proportionate measurement along the Township line". Corner was monumented with a 1" pipe with 4" aluminum cap and the following new bearing trees: 9" Jack Pine S22W 14 links, 9" Jack Pine S55E 17 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M6) Recovered Buckler's monument, as described, in good condition, and at record bearing and distance from his 1963 accessories. Both NBT's are dead: the SW Jack Pine is a stump with scribe marks visible, and the SE is a standing stub with scribe marks visible. Left the monument in place and marked four new accessories as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M6) Fd. 1" pipe with 4" aluminum cap.
Blazed, scribed, and set measuring nails
in the following:

6" Spruce S40E 18.3' "1/4S NBT"
8" J. Pine S69E 12.1' "1/4S NBT"
3" Maple S80E 3.45' "1/4S NBT"
3" Spruce S47N 11.45' "1/4S NBT"

Placed a squared and scribed cedar post
adjacent. Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date July 30, 1996

For the Michigan Department of Natural Resources - Forest Management Division