

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft  
(County)

Located In:

Corner Code #

1. Public Land Survey T46N R 15W E11  
T R  
T R  
S T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R  
4. Lot No. , Recorded Plat  
5. Private Claims

Register of Deeds Stamp & File  
Number

I, Stephan J. Szyszkoski, in a field survey on September 19, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E11) Corner common to Sections 28-29-32-33. 1850 - Established by Guy Carleton Deputy Surveyor. Set post. Spruce Pine 12 N35W 25 links, Spruce Pine 10 S25E 52 links. 1960 - Recovered and recorded by Billy D. Buckler RLS: This corner was re-witnessed as set by U.S. Dept. of Agriculture, U.S. Biological Survey. Concrete [monument] with 3" brass cap. 10" J.Pine N63E 70.5 links, 10" J.Pine N03E 87 links. I note that the USBS performed their work in the late 1930's, during their monumentation of much of the Seney National Wildlife Refuge boundary.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E11) Found the USBS monument as described in the 1960 record, in good condition, and at record bearing and distance from the 1960 NBTs, now both standing dead. Accepted the monument as the best available evidence of the position of the original corner. C/L of M-28 is 89.0' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E11) Found conc. monument with 3" brass U.S. Biological Survey cap. Set measuring nails with MDNR tags in the sides of the following:  
5" Balsam N37E 69.6' mrkd "S28 NBT"  
4" Maple N09E 50.78' "S28 NBT"  
4" Maple N42W 49.8' "S29 NBT"  
5" Balsam N84W 54.35' "S29 NBT"  
Bearings are magnetic.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



Signed by Stephan J. Szyszkoski Date 10/10/07

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS