MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N.R. 16W

		Schoolcraft		oolcraft	COUNTY
DESCRIPTION OF CORNER	†Corner for s	ections 6/5			
CORNER MONUMENT	l" Iron Pipe	with 4" Bra	ss Cap.	<u> </u>	<u> </u>
DATE MONUMENT PLACED AND	WITNESSED 9-19	-61		<u></u>	
WITHESSES TO CORNER	5" W. Birch	(NBT £s)	S18 ^o e	09 3 links	
N	6" W. Birch	(NBT ÈS)	N12 ⁰ W	35 links	
5'	AND				
CIRCLE CORNER REGISTERED					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from (w.pine 24" N56°W 28 links) possible B.T. Unknown party had chopped face on lower part of stump and whittled B.T. on said face. Stump was probably cut too low for any other evidence although curl is visible at top of stump.

SURVEYOR'S SEAL

SIGNED Silly Suckles

BEGISTERED LAND SURVEYOR

DATE __December 29, 1961

Billy D. Buckler