

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 N. R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner for Sections 9-10-15-16

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-12-61

WITNESSES TO CORNER..... 9" Cedar (S9 NBT) N 6°W 28 links



6" Cedar (S15 NBT) S 3°E 28 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at old cedar post set by unknown surveyor. Position fits with good corners West, South and East. No evidence of original B.T.'s.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 13, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler