

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 19 T 47N R 13W S _____ T _____ R _____ S 19 T 47N R 13W	5 (GCDB 140360) 9
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 160340)
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

I, Stephan J. Szyszkoski, in a field survey on 5 9/09/15  
9 9/15/15 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 19) Center-North 1/16th corner between Section 19. Not previously monumented.

(9-Sec. 19) Center-East 1/16th corner, Section 19. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 19) Established the position for the corner midway and on a straight line between Quarter  
corner 1323.05' north and center of Section 19 1323.05' south.

(9-Sec. 19) Established the position for the corner midway and on a straight line between Quarter  
corner 1319.15' east and center of Section 19 1319.15' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set  
measuring nail with MDNR tag in the side of:  
11" W.Pine S41°W 34.63' mrkd "N1/16 BT"  
9" J.Pine S09°E 45.49' do  
10" J.Pine N54°E 45.20' do  
8" W.Pine S64°E 60.27' do  
Set wood post adjacent.  
E= 8078358.369 N= 186624.513

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" J.Pine N74°W 55.87' mrkd "E1/16 BT"  
6" J.Pine N41°W 62.80' do  
6" J.Pine N10°W 54.61' do  
5" J.Pine N84°E 43.84' do  
Set wood post adjacent.  
E= 8078765.409 N= 186227.480

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00  
Coord. Ref.=NGS PID RK0614: N= 185057.887 m. E= 8074174.258 m.

Signed by Stephan J. Szyszkoski Date 11/19/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division, by John Nutkins, PS #52478

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

