

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 19 T 47N R 13W S _____ T _____ R _____ S 19 T 47N R 13W	8 (GCDB 120340) B8
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 140340)
4. Lot No. _____, Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 8 9/09/15
B8 9/15/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 19) Center-West 1/16 corner, Section 19. Not previously monumented.

(B8) Center of Section 19. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 19) Established the position for the corner on a straight line between Quarter corner
1180.60' west (17.87ch.R) and the intersection of 1/4 lines of Section 19 1321.32' east (20.00ch.R),
proportionate to the dimensions derived from the original GLO plat of this township.

(B8) Established the position for the corner at the intersection of straight lines connecting
opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set
measuring nail with MDNR tag in the side of:
11" R.Pine N80°W 2.94' mrkd "W1/16 BT"
6" R.Pine S34°W 19.56' do
8" R.Pine N78°E 12.50' do
7" R.Pine N29°E 13.30' do
Set wood post adjacent.
E= 8077960.793 N= 186215.177

(B8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" W.Pine S66°W 10.19' mrkd "CS BT"
6" W.Pine N57°W 12.80' do
6" W.Pine N35°W 4.25' do
9" W.Pine S58°E 41.95' do
Set wood post adjacent.
E= 8078363.431 N= 186221.333

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00
Coord. Ref.=NGS PID RK0614: N= 185057.887 m. E= 8074174.258 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/19/2015

For the Michigan Department of Natural Resources, Forest Resources Division, by John Nutkins, PS #52478

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

