

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 47.. NR. 14.. W

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 20 and 21 .....

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap .....

WITNESSES TO CORNER 18" Cedar (1/4a NBT) S 32° W 28 Links ..

13" Cedar (1/4a NBT) S 63° E 25 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. This corner was re-established midway and on line between two Section  
corners. No evidence of original corner. Corner lies in wet swamp.

Corner was placed and witnessed June 7, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 8/11/60