

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T 47N R 14W E8
T 47N R 14W D7

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

May 13 1997

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4		3		2		1
3													
4	7			8			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

(E8) Quarter corner common to Section 20-21. Corner reestablished in 1960 by Billy D. Buckler: "This corner was reestablished midway and on line between two Section corners. No evidence of original corner. Corner lies in wet swamp". Description of corner monument: 1" pipe with 4" brass cap. Witnesses: 18" Cedar S32W 28 links, 13" Cedar S63E 25.5 links.

(D7) Quarter corner common to Sections 17-20. Original corner location perpetuated by F.J. Bray in 1956: "Replaced 1/4 corner from one Yellow Pine and one White Pine B.T. in good condition. Description of corner monument: 1" pipe with 4" brass cap. Witnesses to corner: 24" White Pine stp. S77W 60 links, 40" White Pine stp. S13E 110 links".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E8) Recovered the 1960 monument as described, a 1" ID iron pipe capped with a 4" dia. brass MI Dept. of Conservation tablet, in good condition, and at record bearing and distance from the 1960 witnesses, both recovered in good condition. My measurements to adjacent section corners are 2665.72' North and 2644.89' South. I accept the monument as a careful and faithful reestablishment of the position of the original corner. Left the monument in place and marked new witnesses as described below. Corner recovered and re-witnessed by T. Stark and D. Lampela, Newberry District Office.

(D7) Recovered the 1956 monument as described, a 1" ID iron pipe capped with a 4" dia. brass MI Dept. of Conservation tablet, in good condition, and at record bearing and distance from the 1956 witnesses, both in good condition with markings visible. Also recovered the original W. Pine BT S57E 44 links at record bearing and distance. The original BT is still standing with markings visible. Left the monument in place and marked four new witnesses as described below. Corner recovered and re-witnessed by T. Stark and D. Lampela, Newberry District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E8) Found 1" pipe with 4" brass cap.
Blazed, scribed, and set measuring nails
in the following:

24" Cedar S38W 18.95'

18" Cedar S56E 17.4'

5" Maple N46E 2.15' 1/4S NBT

6" Maple N74W 24.45' 1/4S NBT

Placed a 4" squared and scribed cedar
post adjacent. Bearings are magnetic.

(D7) Found 1" pipe with 4" brass cap.
Blazed, scribed, and set measuring nails
in the following:

6" J. Pine N36W 67.45' 1/4S NBT

6" J. Pine S42W 56.35' 1/4S NBT

5" J. Pine S08W 58.15' 1/4S NBT

7" J. Pine S18E 63.45' 1/4S NBT

Placed a 5" squared and scribed cedar
post adjacent. Bearings are magnetic.



Signed by

Stephan J. Szyszkoski

Date

3/25/98

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Forest Management Division