

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47N N.R. 15-16W


Schoelercraft COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 19-30-24-25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-29-69

WITNESSES TO CORNER..... 16" W. Pine (S24 NBT) N40° W 56.9'



10" Soft Maple (S25 NBT) S51° W 37.3'

9" Soft Maple (S19 NBT) N52° E 24.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one Y. Birch bearing N60° W 03 links; a stump cut 6' high. Found remains of old face and scribe marks. Position checks with good corners to east. Found a Beech, 15' north of the corner, blazed on four sides.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 3-24-70  
REGISTERED LAND SURVEYOR