

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47-18 NR 16 W. . .

----- Schoolcraft ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5, 6, 31, 32 . . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap, . . .

WITNESSES TO CORNER 5" B. Spruce S 60° E 79 links. . .

No other witnesses available.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replace Section Corner from 3 Tamarack B.T.'s in good condition.

Corner has been set by H. Lawrence, Surveyor.

Corner found by Ken Killmar.

Corner placed and witnessed January 18, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 2/14/56
REGISTERED LAND SURVEYOR