

DATE 1993

SHIAWASSEE

RECORDED

93 DEC -6 AM 11:00

REGISTER OF DEEDS

SHIAWASSEE COUNTY, MICH.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
REMONUMENTATION

For corners in
Shiawassee

	(County)	Located In:		Corner Code #
		6N	1E	
1. Public Land Survey		T	R	M-12
		T	R	
		T	R	
		T	R	
2. Property Controlling in Section		S	T	
		S	T	
3. Miscellaneous		S	T	
Property in Sec.		S	T	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Norman C. Caldwell, in a field survey on November, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-12 E 1/4 cor., Sec. 36, T6N-R1E

Wood post placed by J. Wampler, 1826
S29°W 20 lks. (13.20') 10" Beech
N77°W 21 lks. (13.86') 6" Ironwood

Survey by Ezra Mason, 1869, recorded in
Book A, S.C.R.
S26 1/2°E 44 lks. (29.04') 16" sugar
S84 1/2°W 46 lks. (30.36') 12" Sugar

Survey by L. A. Bryan, 1986 - 1987, recorded in
L. 2, pg. 478 of Corners and L. 5, pgs. 516 - 519
& 650 - 652.
Set 1/2 bar and cap midway and on line b/w NE & SE
cor. Sec. 36, cor. 1.5' West of N & S fence & 20'
South of fence line East

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-12 E 1/4 cor., Sec. 36, T6N-R1E

Fnd. no evidence of County Surveyor's references,
Fnd. 1/2" bar w/cap #25832 per L. 2, pg. 478 of
Corners and L. 5, pg. 516 - 519 & 650 - 652.
Replaced with a standard 20" Harrison marker as
approved by the Shiawassee County Peer Review Group
and is accepted as the best available evidence of
the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-12 E 1/4 cor., Sec. 36, T6N-R1E

Fnd. no evidence of County Surveyor's references, Fnd. 1/2" bar w/cap
#25832 per L. 2, pg. 478 of Corners and L. 5, pg. 516 - 519 & 650 - 652.
Replaced with a standard 20" Harrison marker as approved by the Shiawassee
County Peer Review Group and is accepted as the best available evidence of
the position of the original corner.
N15°W 24.59' Set spike 20" Oak (R - tree)
South 15.22' Set spike W. face 22" Oak (R - tree)
West 28.00' Set spike N. face 18" Beech (R - tree)
N07°E 19.64' Fnd. 40d spike over large rock
(may represent closing corner)
South 1'± Set REI Carsonite Witness Post



Signed by Norman C. Caldwell
Surveyor's Michigan License No. 12018

Date 2 DEC 93