DSD 1 0 1993

For corners in

## RECORDED

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 REMONUMENTATION

90 DEC - 5 AIII: 00 WELFARED OF HELDS Spiga planethe

Located in: Corner Code ## 6Ν 1E M-13 .R. Ť \_\_\_\_\_ R \_\_ \_ R \_

egye yan aranaty, Mich.

1. Public Land Survey \_ R . \_\_ T \_ **Property Controlling** \_\_ R \_ \_\_\_ T \_\_\_\_\_ R \_ S in Section S \_\_\_\_ T .\_\_\_ R \_ Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat \_ 5. Private Claims \_\_\_

Norman C. Caldwell November in a field survey on

93

19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

м-13 Twp. cor., common to T5 & 6N - R1 & 2E

Wood post placed by J. Wampler, **1824** s29°W 8 lks. (5.28') 23" W. Oak N42°W 32 lks. (21.12') 23" W. Oak

Surveys by J. F. Quine, 1967 - 1975, recorded in L. 1, pg. 558 of Corners and Field Book 13, pg. 111, reestablished Set 5/8" x 24" iron rod stake in evidence of old corner post hole. Put stones around it and set pointed stone on S. side iron NO5°W 26.2° 24" Oak
5% 10.7° 10" Oak
555 4 01 12" Oak

6.0' 12" Oak 18.9' 6" Hickory 2.0' (1.6' E & 1.0' N) ESE 18.91 ΝE NEW fence cor. post (Ref. to center) Survey by M. L. Vanraemdonck, 1983, recorded in L. 4, pg. 49 of Surveys, Fnd. 3/4" iron rod \$45°W 10.13' Nail 12" Oak North 25.25' Nail 23" Oak

S45°F 5.70' Nail 13" Oak

Unrecorded survey by A. F. Miller, 1978,

fnd. iron rod 30" Oak

N05°W 26.20' 945°W 10.70' 965°E 6.00' 12" Cak 14" Cak 6.00

N45°E 18.90 8" Hickory

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-13 IMP. cor., common to I5 & 6N - R1 & 2E

> Fnd. 5/8" rod surrounded by rocks in old N. S. E. W. fence per L. 1, pg. 558 of Corners & L. 4, pg. 49 of Surveys. Also, fnd. 1/2 rod w/cap #12024 (Miller) along side. Replaced with a 20" standard Harrison marker as approved by the Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13 Iwp. cor., common to T5 & 6N - R1 & 2E

Fnd. 5/8" rod surrounded by rocks in old N. S. E. W. fence per L. 1, pg. 558 of Corners & L. 4, pg. 49 of Surveys. Also, fnd. 1/2 rod w/cap #12024 (Miller) along side. Replaced with a 20" standard Harrison marker as approved by the Shiawassee County Peer Review Group and is accepted as the best available

evidence of the position of the original corner.

S45°W 10.66' Fnd. overgrown nail, reset N & T #12018 W. face 15" Oak (R)

N05°W 25.83' Fnd. N & T #25832 SW face 30" Oak (R)

N65°W 24.37' Set N & T #12018 S. face 12" Nickory

S55°E 12.18' Set N & T #12018 SSW face 6" Oak

Signed by

A CONTRACTOR OF THE STATE OF TH

5

Norman C. CALINELL PROFESSIONAL SURVEYOR

No. 12018

Surveyor's Michigan License No. .

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Date