

# SURVEY & REMONUMENTATION

DEC 15 1993

## COMMISSION

For corners in  
Shiawassee

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

### REMONUMENTATION Corner Code ##

Located In:

	6N	2E	K-11
1. Public Land Survey	T	R	
	T	R	
	T	R	
	T	R	
2. Property Controlling in Section	S	T	R
	S	T	R
3. Miscellaneous Property in Sec.	S	T	R
	S	T	R

RECORDED

93 DEC -6 AM 10:59

REGISTER OF DEEDS

SHIawassee COUNTY, MICH.

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Norman C. Caldwell, in a field survey on November, 19 93,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

### A. Description of original monument and accessories and/or subsequent restoration:

K-11 Sec. cor., 25, 26, 35 & 36, T6N-R2E

Wood post placed by J. Wampler, 1826,  
N03°E 38.5 lks. (25.41') 15" Elm  
S62°W 37 lks. (24.42') 15" Elm

L.C.R.C., K. R. Piotrowski, 1973, recorded  
in L. 1, pg. 146 of Corners,  
Fnd. 1/2" pipe  
SW 23.75' NE cor. conc. bridge post  
SE 24.25' NW cor. conc. bridge post

Unrecorded survey by R. L. Mitchell, 1973  
Fnd. 1/2" pipe  
SW 23.75' NE cor. conc. bridge post  
SE 24.25' NW cor. conc. bridge post

Surveys by B. Griggs, Jr., 1974, recorded  
in L. 2, pgs. 113 - 120 of Surveys,  
Fnd. 1" pipe  
S30°E 23.43' NW cor. conc. bridge post  
S30°W 23.06' SW cor. conc. bridge post  
N70°W 55.78' Nail in Power Pole  
N30°W 72.56' Nail in Power Pole

Surveys by M. L. Vanraemdonck, 1992 - 1993,  
recorded in L. 6, pgs. 197 - 198 & 564 - 566.  
Fnd. 1/2" pipe  
N35°W 71.92' N & T S. face Power Pole  
S60°W 46.54' N & T N. face Power Pole  
N35°W 71.92' N & T S. face Power Pole

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-11 Sec. cor., 25, 26, 35 & 36, T6N-R2E

Fnd. 1/2 pipe in mon. box in CL Morrice Road  
and 54'± N. of Looking Glass River, per L. 1,  
pg. 146 of Corners, and L. 2, pgs. 113 - 120 &  
L. 6, pgs. 197 - 198 & 564 - 566 of Surveys.  
Replaced with a standard 20" Harrison Marker as  
approved by the Shiawassee County Peer Review Group  
and is accepted as the best available evidence of  
the position of the original corner.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-11 Sec. cor., 25, 26, 35 & 36, T6N-R2E

Fnd. 1/2 pipe in mon. box in CL Morrice Road  
and 54'± N. of Looking Glass River, per L. 1,  
pg. 146 of Corners, and L. 2, pgs. 113 - 120 &  
L. 6, pgs. 197 - 198 & 564 - 566 of Surveys.  
Replaced with a standard 20" Harrison Marker as  
approved by the Shiawassee County Peer Review Group  
and is accepted as the best available evidence of  
the position of the original corner.  
S50°W 46.57' Fnd. Landmark N & T E. face Power Pole (R)  
N10°W 71.92' Fnd. Landmark N & T S. face Power Pole (R)  
S30°W 23.11' NE cor. conc. bridge rail footing (R)  
S30°E 23.45' NW cor. conc. bridge rail footing (R)



Signed by Norman C. Caldwell Date 2 DEC 93

Surveyor's Michigan License No. 12018