

SURVEY & REMONUMENTATION

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 NOV 16 PM 3:41

For corners in

Shiawassee
(County)

Located in:

Corner Code #

REGISTER OF DEEDS

Haye Shubbs
SHIawassee COUNTY, MICH.

1. Public Land Survey T 7N R 2E (K-13)
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Mark L. VanRaemdonck, in a field survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1.) Original: Joseph Wampler, D.S. 1824.
Monument: Wood post
Accessories: B. Oak 24 N6°E 31
W. Oak 14 S31½°W 40
- 2.) O. M. Elliot: Book 41, page 61. 4/9/65.
Monument: Not given.
Accessories: Power pole NW 77'
Dead end post East 26.6'
R.R. tie corner post East 32.7'
Road name sign post NW 54.8'
Telephone pole NW 57.80'
- 3.) Bernard Griggs: Survey recorded Liber 2, page 10. 5/16/74.
Monument: Found 1" pipe
Accessories: S35°W 24.73' 18" Hickory
S70°W 66.3' Util. pole
- 4.) M. VanRaemdonck: Survey recorded Liber 4, page 489 and Liber 4, page 152.
Monument: Found ½" pipe
Accessories: North 10.3' Centerline asphalt
S35°W 24.73' 18" Hickory
S70°W 66.3' Telephone pole
N45°W 64.46' 24" Hickory

APPROVED

County Remonumentation
Peer Review Group
10/18/94 M.L.V.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Accessories from no. 2 above have been obliterated. Found pipe as referenced in no. 3 and 4 above. Accepted this as the best available evidence of the original corner location.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories:
S05°E 16.95' E. edge E. leg double arrow sign
S20°W 24.42' Set N&T E. face 24" Hickory
S80°W 66.18' SE face util. pole
N30°W 64.25' Set N&T E. face 26" Hickory
North 0.65' S. edge asphalt surface



Signed by Mark L. VanRaemdonck

Date Nov. 11, 1994

Surveyor's Michigan License No. 24622

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971
REVISED MAY 14, 1971
REVISED JAN., 1981

LIBER 1R **PG** 76