SURVEY & REMONUMENTATION

SEP 2 9 1994

For corners in COMMISSION

5. Private Claims ___

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code ##

RE	CO	R	D	E	D
----	----	---	---	---	---

94 SEP-6 AM 11:05

REGISTER OF DEEDS

SHIAWASSEE COUNTY, MICH.

M-11 T 7N R 4E T ____ R _ _ R . __ R _

Register of Deeds Stamp & File Number

Shi awassee (County) Public Land Survey Τ_ **Property Controlling** __ R _ __ T ___ R _ S ... in Section __ T ____ R __ Miscellaneous R Property in Sec.

___ , Recorded Plat .

Located in:

Norman C. Caldwell , in a field survey on	July	19 94
do hereby certify that under requirements of P.A. 74, Michigan F in lines 1 and 2 above were in conformance with regulations	P.A. of 1970, the corner poi	ntsmentioned
current manual of survey instructions of the United States Dep	partment of the Interior, B	ureau of Land
Management or by a decree of a Court of Law and/or that the co above were in conformance with the rules of the Michigan Boar	rd of Land Surveyors or by	a Decree of a
Court of Law; established, re-established, monumented, respressed below:	re-monumented, recover	ed, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- ß 10 12
- A. Description of original monument and accessories and/or subsequent restoration:
- Sec. cor., Secs. 25 & 36, 17N-R4E

Wood post placed by J. Wampler, 1822 N18°E 15 lks. (9.90') 8" Ash N71 1/2° 2 lks. (1.32') 6" Maple

Survey by E. Mason, C.P. Co. surveyor, 1866 recorded in Co. Surveyors records pgs. 78-79 and BK C pgs. 62-63 Mon. & Refs. Not Given

Mich. St. Highway Const. Plans,1957, C.S. #76023 sheet No. 16 Brewer Eng. Mon. & Refs. Not Giver

Survey by O.M. Elliot, 1958, field BK 31 pg. 42 Box in Pav't No Refs. Given

Survey by O.N. Elliot, 1958, recorded plat of "Supervisors Plat of Gansseey's Sub." L. 1, pg. 200 of Plats

Survey by E.J. McCombs, C.P. Co. 1972 recorded in L. 1, pg. 79 of corners.

Mon. Box 3.5' W of CL Pav't

\$50°W 61.00' Power Pole

N50°W 62.15' Road Sign

N45°W 68.50' 4" Cedar

Survey by J.F. Quine, 1975 recorded in t. 1, pg. 494of corners. Iron stake in cast iron mon. box.

Unrecorded surveys by R.H. Kraft, 1988 Mon. & Refs. Not Given

Survey by N.C. Caldwell, 1989 recorded in L. 5, pg. 294-295 of surveys and L. 2, pg. 624 of corners. Fnd. iron in mon. box per MDOT r/w plans North 376.3' SW cor. Sec. 31, I7N-R5E

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Sec. cor., Secs. 25 & 36, T7N-R4E M-31

Fnd. 1/2" rerod w/REI cap in mon. box. During excavation to replace 1/2" rerod w/a std. 20" Harrison marker, fnd. 2" steel shaft 16" long 1.2' below asphalt. Held position as approved by the Shiawassee County Remon. Peer Review Group and is accepted as the best available evidence of the position of the original corner.

APPROVED

County Remonumentation Peer Review Group 8/14/94 MLV

STATE OF MICHIGA

NORMAN C. CALDWELL

BURVEYOR

- Description of monument for corner and accessories established to perpetuate locating the position of the corner: `.C.
- M-11 Sec. cor., Secs. 25 & 36, T7N-R4E

Fnd. 1/2" rerod w/REI cap in mon. box. During excavation to replace 1/2" rerod w/a std. 20" Harrison marker, fnd. 2" steel shaft 16" long 1.2' below asphalt. Held position as approved by the Shiawassee County Remon. Peer Review Group and is accepted as the best available evidence of the position of the original corner.

NO°11'57"E 376.64' Fnd. 1/2" rerod w/cap at Sec. cor. Secs. 30 & 31, T7N-R5E (R) S67°W 61.10' Fnd. N & T N. face Power Pole (R) N68°W 46.90' Set Chis. "+" N. end 18" CMP

34.59' N. leg traffic sign (<-->)

Date

Signed by

FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAH., 1983

Surveyor's Michigan License No.