SURVEY & EVONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

2000 Remonumentation Program

JAN 1 6 2001

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

SECTION

SHIAWASSEE (County)	Located In: Venice Twp.	Corner Code						3044 12/0	414 4/2000 D-284	1 09 53A
1. Public Land Survey	T <u>7N</u> R4E T R T R	<u>C-5</u>	Kaye Gru	Register	er of Deeds Stamp & File Number					
2. Property Controlling S In Section S 3. Miscellaneous S	T R T R T R T R		County F	ROV Remonume Review Gr	ntation					
Property in Sec. S	'			Leview Ci	A B C	D	E F 6	H :	JΚ	L:Ŵ
4. Lot No, Recorded Plat 5. Private Claims				2 3	6	5	4	3	2	1-7
I. John H. Rauser, P.S.	in a field survey on	August	:	20 00 5	7-	8	···• ø	10	11	12-
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 6 current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 8 Court of Law; established, re-established, monumented, re-monumented, recovered, found as of					18	17	1ŏ	15	14	13
					19	20	21	22	- 23	24
expressed below:	abiisiled, monumer	nted, le-monumen	nica, recovered	10	30	29	28	27	26	25
NOTE: Not more than 4 corners on this certificate.	s, all in the same	town and range	e, may be rece	orded 11 12	31	32	-33	34	35	-36
A. Description of original n		_		13		<u>::</u> _	1		<u></u>	1 1
Manle C-5 to C-	J. Wampler, D.S., 4 = 40 ch (2640'), 74, Monument D	Set wood post, C-5 to C-6 = 40	witnessed by I ch (2640'), C-	N15W 23lks (1 5 to D-5 = 40.1	5.18') 10 15 ch (26)" Mapi 349.9"}.	C-5 to E	3-5 = 4(3 ch (26	540'} :
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Section Corner common to Section 7, 8, 17 & 18, T7N-R4E, Venice Township, Shiawassee County Found no evidence of the original government corner or accessories. Found ½" re-rod with cap #24622 in the approximate centerline of Vernon Road. Upon excavation, discovered a bent T-iron 0.6' below grade and crockery 2' below surface. Measured South to C-6 = 2646.90', North to C-4 = 2641.01', West to B-5 = 2640.42'. Found no conflicting evidence in the vicinity of the found re-rod. We recommend that the found T-iron be accepted as a careful and faithful perpetuation of the position of the original government corner and be replaced with a standard Shiawassee County Harrison monument and place a monument box.										
				•			•	*		
N40E 52.81' Set nail N45W 46.95' Set nail	to Section 7, 8, 17	7 & 18, T7N-R4E son monument South face of tele Northwest face of ortheast face of 7	Venice Towr and monume ephone pole of 6" Oak "Spruce	nship, Shiawas ent box	oF M	inty ICHICA	ie posi	tion o	f the	
Signed by Surveyor's Michigan License No	39096	ausy	•	* LICENSE	JOHN RAUSI ROFESSII SURVEY No. 39096	ER ONAL OR	LEYOR &	AND SU	9/b	0 IAN. 28, 197