## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY & REMONUMENTATION

	, and	•	A KONSET OF THE PARTY OF THE PA
For corners in	Located in:	Corner Code #	NOV 0 3 1998
Shiawasses (County)			SECTION
Public Land Survey     Property Controlling	T_8N_R_2E TR TR TR STR		Register of Deeds Stamp & File Number
In Section	SR		3007699 Page: 1 of 1
Miscellaneous     Property in Sec.     Lot No.	STR , Recorded Plat		10/27/1998 03:22P
5. Private Claims		Kaye Gru	pps - direction
ines 1 and 2 above were in the current manual of interior, Bureau of Land N comer points mentioned if the Michigan Board of Land National and Michigan Board of Land National American	in conformance with regulated urvey instructions of the United Management or by a decree of in lines 3, 4 and 5 above were and Surveyors or by a Decree of re-monumented, recovered	of a Court of Law; established, i, found as expressed below:	of 3 - 10 - 11 - 12 - 15 - 14 - 13 - 15 - 14 - 13 - 15 - 14 - 13 - 15 - 14 - 13 - 15 - 14 - 15 - 15 - 14 - 15 - 15 - 15
NOTE: Not more that recorded on this cer	in 2 corners, all in the sartificate.  al monument and accessori	ame town and range, may es and/or subsequent restorat	ion: 8 -19 -20 -21 -22 -23 -23 -23 -23 -23 -23 -23 -23 -23
Original, Joseph Wamph     Monument: Wood post     Accessories: W Oak 30     do 30	N86°W 84	ok B, page 61, August 1855	11 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
2. Andrew Huggins, County No monument or access	N21°E 62 y Surveyor, County Surveyors Book A	720 244 245, August 5 & 6, 1872	10
3 Ezra Mason, County Sul	Neyor, County Surveyors are given.		ans 76012-B-C2, Sheet 7
4. John Quine, LCRC, rec	placed in cast iron monument bo	X. Accessori	ns 76012-B-C2, Sheet 7 with large stone es: N25°E 71.33° 36" stump, N65°W 55.43' NE cor. es: N25°E 71.33° 36" stump, N65°W 55.43' NE cor. orw 55.90' NE cor. hdwl., S25°E 57.06' P.Pole
5. Mark L. VanRaemdond Monument: Found iron Accessories: South S25°E S80°W	k, Certified Survey, records block in monument box 2.64 NW cor. Section 57.05 Pole NE corner of HD	WL.	APPROVED  County Remonumentation
6. Mark L VanRaemdonc	ik, Certified Survey, recorded Libe sories same as No. 5 above.	r 5, page 24, 71-9-117	Peer Review Group
7. Mark L. VanRaemdor Monument and access	sories same as No. 5 above.		Peer Heview Group  NCC / SCT 98
8. Jan Fokens, Certifled Monument and acces	Survey, recorded Liber 3, page 5 sories same as No. 5 above.	4 mane 637, September 23, 196	of the state of th
9. Mark L. VanRaemdor Monument; Found 1" Accessories; South SOCE N3OE	nck, Certified Survey, recorded in pin in monument box 2.65 Center of Mon 57.35 NW face util: 40.77 Sedge gas pil 57.95 SW face pow	peline marker post er pole	HARK L  VANRAEMDONCK  PROFESSIONAL  SURVEYOR  No.  24022  OPESSIONAL  No.  1100  110
an atom Coldwell, LCI	RC, recorded Liber 2, page 658,	August 3, 1989	24822
Cel	Hilled Survey, recultory man, ", "	- <b>-</b>	2 ROPESTON AMILIA
12. Mark L. VanRaeme	donck, Certified Survey, 9 above.		or re-establishing corner:
B. Description of C Found 1"F evidence in Huggins	corner evidence found and/o pin in monument box as refere Measured distance between L s survey, 37.90 chains or 2501	r method applied in restoring onced in No.s 5 and 9 above. For -9 and M-9, 2504.31 feet fits we -40 feet. I accepted this location dence.	und no conflicting Ill with distance shown as the original corner
C. Description of treplaced stamped	S DOE JAMAS ALL	cesscrites that the standard Shawassee Couling a Standard Shawassee Couling accessories and by the following accessories	ing the position of the corner. nty Harrison Marker Monument, ss:
<b></b>	an ore salitificated to the control of the control	ALL STATE OF THE S	

MDOT tag in S face util pole Set N&T 24622 in NW face util. pole 3/4" pin in monument box cor. A-9 T8N-R3E centerline asphalt surface M-52 SW cor. catch basin casting

88.80' 57.43' 2.62' 45.37' 79.38'

Surveyor's Michigan License No. 24622

Date OCT. 8, 1998