

APR 08 1996

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **COMMISSION**  
Shiawassee  
(County)

Located In:

Corner Code #

RECORDED

95 SEP -5 PM 1:49

REGISTER OF DEEDS

*L. J. Shubert*  
SHIAWASSEE COUNTY, MICH.

Register of Deeds Stamp & File Number

1. Public Land Survey T 8 N R 4 E K-12  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Norman C. Caldwell, in a field survey on May 24, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-12 Post set by J. Wampler 1822  
N 82 W 22 lks (14.5)  
16" Lynn S 8 W 10 lks (6.6) 4" Birch

Survey by L. Mason Co. Survey 1876, P 92 & 93,  
Co. Survey record and Ezra Mason, May 23, 1881  
placed post...  
S 38 1/4° E 60 lks (39.6') 1" Hickory  
S 38 1/4° W 58 lks (38.28') 30" W. Oak Stump

L.C.R.C. dated November 1971 by E.J. McCombs L.S. No. 10696 L 1 P 17  
Found "T iron"  
N 15° E 99.36' Nail in 18" Ash  
S 85° W 23.15' Spike in C/L of stump  
East 24.6' W face of F. Cor. post

L.C.R.C. dated July 6, 1973 by K.R. Piotrowski L.S. NO. 9685, L 1 P 158  
found bent "T" bar-Replaced W/ 1/2" Re-Rod 4" below road  
No References

Survey by A.F. Miller L.S. No. 12024 Oct 11, 1973, L 1 of Survey P 514-516  
Found 1/2 Re-rod 4" below road surface

Survey L 2 P 502 by J.S. Fokens L.S. 21567 June 1, 1977  
Fnd Rod W/cap  
N 60 W 23.05' NE cor N. Oak  
S 45 W 23.15' SE " " "  
S 85 E 39.45' Bolt in cable marker

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found record 1/2" bar in C/L gravel road per  
L 1 P 17, 158, & 514, L 2 P 502.  
There is no apparent conflicting evidence.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/4 corner 35 & 36, T8N, R4E May 24, 1995  
Found record 1/2" Bar in C/L Gr. Road in Line W/Field Line east, per  
L 1 P 17, 158, & 514, L 2 P 502  
Replaced W/ Harrison marker and is accepted as the best available  
evidence of the position of the original corner.  
N 45 W 24.91' Chiseled "X" in top C/L cong, hdwl.  
S 45 W 25.04' Chiseled "X" in top C/L cong, hdwl.  
S 88 E 63.05' 12018 Tag in N. Face 8" Red Pine  
N 10 E 149.24' 12018 Tag in W. Face 24" Maple  
S 35 E 42.13' 12018 in W face 10" Red Pine

APPROVED 7/25/95  
County Monumentation M.L.V.  
Peer Review Group

Signed by *Norman C. Caldwell* Date 5 JULY 1995

Surveyor's Michigan License No. 12018

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983  
ADAPTED FOR WORD PROCESSING MARCH, 1993

LIBER 1R PG 113