DEC 0 2 1993

COMMISSION

1993 Remonumentation program

I AND CORNER RECORDATION CERTIFICATE

THAND COURT DECOUDATION CELLIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
HIMTATA TOUNCUID

For corners in TUSCOLA	Located In:	JUNIATA TOWNSHIP Corner Code -++	A. 1970	7. A 20 M	0. #6 1979 22 PH 2	O FOR RE
Public Land Survey	T R			SOUTH THE STATE OF	714	1080 1080
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R		Register of De	eeds Stamp	» & File Numb	er
4. Lot No, 5. Private Claims,	Recorded Plat		2 A B C	C D E F	G H J	K L !
do hereby certify that under re in lines 1 and 2 above were current manual of survey insti Management or by a decree of above were in conformance w	equirements of P.A. 74, Michigan f in conformance with regulations ructions of the United States De f a Court of Law and/or that the co rith the rules of the Michigan Boa	y 11, 19 93. A. A. of 1970, the corner points mentions and rules therefore as required in partment of the Interior, Bureau of Lorner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree re-monumented, recovered, found	ned 6 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	8 9 9 16 16 16 16 16 16 16 16 16 16 16 16 16	15 14	13-

A. Description of original monument and accessories and/or subsequent restoration;

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

1821 G.L.O. Notes Joseph Wampler, D.S. Set 1/2 mile post Ash 16" S37°W 8.58' Ash 15" N75°E 3.30'

on this certificate.

Aug., 1973 Act 74 Juniata Township, Page 14 by David T. Rowe,

R.L.S. #11192. Found 1 1/4" pipe.

South 88.26' 1 1/4" pipe at West 1/4 corner, Sec. 7, Indianfields

Township.

North 5.5' fence list West.

(this corner incorrectly recorded as corner M-4)

Section A. continued on back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found and accepted 1" pipe (bent) dug below pipe and found no other evidence. Dug at split of measured mile and found no evidence of corner.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Removed 1" pipe and set standard monument with 2" brass cap stamped corner M-2, T12M-R8E. S00°13'40"E 45.00' found 5/8" re-rod at centerline of o. h. power line E. & W.

S00°13'40"E 45.00' found 5/8" re-rod at centerline of 0. II. power line E. a N. S00°12'20"E 88.28' found 1 1/4" iron pipe @ apparent cor. A-4, T12N-R9E.

S37°30'W 65.85' set T.C. Re-mon. tag & spike over #11192 tag in SE face S. tower leg. S47°15'W 54.11' set T.C. Re-mon. tag & spike over #11192 tag in SE face N. tower leg. N47°00'E 74.69' set T.C. Re-mon. tag & spike over nail & disc in N. face p. pole. N69°21'W 11.15' found p. k. nail in S. face of 6" wood corner post.

<u>235</u>03 Surveyor's Michigan License No.

Date Oct. 11, 1993

FORM APPROVED BY MICHIGAN STATE

STATE OF MICHIO KENNETH D DUNTON ¥ LAND SURVEYOR No. เ**2รับโคโซ**Yor

OFESSIO HABER

APPROVED

Continued from Sec. A. on front of this form.

Nov. 2, 1988 Act 74, Juniata Township, Page 50 by Stephen J. Szyszkoski, R.L.S. #33986. Found 1" pipe.

\$40°W 65.68' found tag #11192 in p. p.
\$45°W 53.97' found tag #11192 in p. p.
\$80°E 29.60' set p. k. nail in SW face 6" dia. wood fence post.
N70°E 18.11' set p. k. nail in S. face 6" dia. wood corner post.
North 5.5' fence line West.
South 88.26' 1 1/4" pipe at W 1/4 cor. Sec. 7, T12N-R9E.

