

1997 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD
LIBER NO. _____ PAGE NO. _____
FILED #40
ELLINGTON TOWNSHIP
97 OCT -7 PM 3:03
TUSCOLA COUNTY
REGISTERED DEEDS

For corners in: ELLINGTON TWP.

<u>TUSCOLA</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 13N R 10E	D-13
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, JONATHAN M. FIELD, in a field survey on JULY 24 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:
1834 GLO; PARKE, D.S.; SET 1/4 SEC. POST; PINE 50 N27W 9LKS., PINE 36 N31E 20LKS.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1997 ROWE; FIELD, PS#37276; FND. NO EVIDENCE OF MONUMENT AT CORNER POSITION; RE-ESTABLISHED CORNER
POSITION BY SINGLE PROPORTION BETWEEN CORNERS C-13 & E-13 T13N-R10E AND ON LINE FROM E-13
T13N-R10E THROUGH FND. T-IRON AT APPARENT D-1 T12N-R10E

ACCEPTED SINGLE PROPORTION AS BEST RE-ESTABLISHMENT OF THE ORIGINAL CORNER POSITION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
D-13 SET STD. REMON. MONUMENT STAMPED D 13 T13N R10E
EAST, 43.19' FND. T-IRON APPARENT D-1 T12N-R10E
N25°E, 33.10' SET NAIL W/TAG #37276 IN SE FACE 18" CHERRY
S58°W, 39.74' SET NAIL W/TAG #37276 IN SE FACE 8" CHERRY
S53°W, 36.56' FND. 2" PIPE
S64°E, 41.28' SET NAIL W/TAG #37276 IN N. FACE 14" CHERRY
N51°W, 42.44' SET NAIL W/TAG #37276 IN NW FACE 8" CHERRY

Signed by Jonathan M. Field Date 9-24-97
Surveyor's Michigan License No. 37276



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1979
REVISED JAN. 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

APPROVED
9-22-97

SURVEY &
REMONUMENTATION

NOV 26 1997

COMMISSION

