LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

			CATED IN-:		CORNER CO	IE NUMBER		
1. PUBLIC	LAND SURVEY	<u>22</u> т	15 N., R.	_8E.	<u>I-7</u>			
2. PROPER	TY CONTROLL- NG IN SECTION-	,T	N. S., R.	E. W.				
	, I							
	E CLAIMS							
5. PRIVATE	E CEAINS						REGISTER OF DEEDS STAMP AN FILING NUMBER	D
the corner pre-established and rules the Bureau of I and 5 above as expressed	points mentioned ed, monumented, herefore as requin Land Managemen e were, in a field	in lines 1 a re-monumed in the a at or by a d survey on_	and 2 above nented, recove current manu- lecree of a co	were, in a vered or remail of survey ourt of law.	field survey on stored as express by instructions of Furthermore, 19, found,	octobe sed below and the United S hat the corne recovered, res	of P.A. 74, Michigan P.A. of 18 er, 19 79, establish in conformance with regulat states Department of the Interpoints mentioned in lines 3 tored, established or re-established for Land Surveyors or, but the points of the points mentioned in lines 3 tored, established or re-established or re-established or the points of the	hedion rion 3, 4
A. Descrip	ntion of original n	nonument a	and accessori	es and/or :	subsequent resto	ration:		
1-7	McCann set Witnesses	1" pipe S 5 ⁰ W N 4 ⁰ W	with bra 49.41'	ss cap 1 Quad 5" Twin 5"	flush with o Thornapple Thornapple	round.	AcCann in April, 1971.	
B. Descrip	tion of corner ev	idence foui	nd and/or m	ethod appl	ied in restoring	or re-establishi	ng corner:	
I-7	Found 1" pi	pe with	brass ca	p as se	t by A. V. I	lcCann.		
I-7	Found 1" pi	pe with	brass ca	p as se	t by A. V. I	lcCann.		
							e position of the corner:	
C. Descrip		nt for corne h brass 41' Qu 72' Tw	er and access cap. ad 5" Tho in 5" Tho	ories estab	lished to perpetu		e position of the corner:	
C. Descrip	otion of monumer 1" pipe wit S 50 W 49. N 40 W 23. East 17.0'	nt for corne th brass 41' Qu 72' Tw & Auto	er and access cap. ad 5" Tho in 5" Tho Trail	ories estab ornapple ornapple	lished to perpetu	ate locating th	e position of the corner:	
C. Descrip I-7 SIGNED F	otion of monumer 1" pipe wit S 50 W 49. N 40 W 23. East 17.0'	nt for corne th brass 41' Qu 72' Tw £ Auto	er and access cap. ad 5" Tho in 5" Tho Trail	ories estab	lished to perpetu	ate locating th	e position of the corner:	
C. Descrip I-7 SIGNED F	otion of monumer 1" pipe wit S 50 W 49. N 40 W 23. East 17.0'	nt for corne th brass 41' Qu 72' Tw £ Auto	cap. cap. ad 5" Tho in 5" Tho Trail	ories estab	lished to perpetu	ate locating th	(SEAL)	
C. Descrip I-7 SIGNED F SURVEYOR FOR STATE	otion of monumer 1" pipe wit S 50 W 49. N 40 W 23. East 17.0'	nt for corne th brass 41' Qu 72' Tw £ Auto	cap. cap. ad 5" Tho in 5" Tho Trail	ories estab	lished to perpetu	DATE		
C. Descrip I-7 SIGNED F SURVEYOR FOR STAT	otion of monumer 1" pipe wit S 50 W 49. N 40 W 23. East 17.0'	nt for corne th brass 41' Qu 72' Tw C Auto	cap. cap. ad 5" Tho in 5" Tho Trail ATION NO. S AGENCIE	ories estab	lished to perpetu	ate locating th	(SEAL)	