MAY 0 5 1997

1996 REMONUMENTATION PROGRAM

CO	M١	Al.	SSI	ON
	40.12		-	

COMMISSION	LAND CORN Filing Requ	IER RECORDATION IF THE RECORDATION IN THE RECORDATI	ON CERTIFICAT		130	S :: 5	, 117
For corners in N. Akron Tw	р.		4			国员	CHINA CHINA
Tuscola Loca	ated In: Co	orner Code #				AT A	B 79
1. Public Land Survey	T15NR 8E T R T R	G-13				PK 3: 39	0 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
2. Property Controlling S in Section S 3. Miscellaneous S Property in Sec. S	T R T R T R T R T R T R T R T R T R T R			Register	of Deeds St	amp & File N	<del>-10</del>
4. Lot No, Recorded Pl 5. Private Claims Kenneth D. Dunton in a			by state that under	A B C 1 2 6 3 4 7	D E F (	3 H 1 J	K L M
requirements of P.A. 74, Michigan P.A. of conformance with regulations and rules the United States Department of the Interior, that the corner points mentioned in lines Board of Land Surveyors or by a Decirecovered, found as expressed below:	of 1970, the corner points erefore as required in the o Bureau of Land Manageme 3, 4 and 5 above were In c ree of a Court of Law; e	mentioned in lines 1 and urrent manual of survey ent or by a decree of a Co onformance with the rule stablished, re-established	d 2 above were in instructions of the burt of Law and/or so of the Michigan ed, monumented,	5 - 19 - 7 8 - 19 - 9	17-16-		13-
NOTE: Not more than 2 comers, all on this certificate.	in the same town and ra	nge, may be recorded		10 30 11 12 31 31	-2928 	3435	25
A. Description of original monumen	t and accessories and/	or subsequent restora	ation:	131-1. 1			
G.L.O. 1821 Joseph Wampler, D.S Set post corner Sec Ash 8 S72E 67 Ash 9 N64W 206		Dec. 26 to R8E by G. E Prev. set p April 12 to R8E by L. M Post, stone Locust 8 N	B. Felton, post & ston 18, 1906 I. Brumley, es & crocke	County e at c Survey Count ery at	Survey orner. of Sec y Surve corner.	or No acce tion 34 yor.	ssories , Tl5N-
Note: Section A co.	ntinued on ba	ack of form.					1.35 1/2
B. Description of corner evidence Found nothing. Re- Section 34 by L. M	-established	pplied in restoring or r corner prop	eestablishing corne ortional t	er: o 1906	resurve	ey of	2
C. Description of monument for col	en or and acceptains as	etablished to pernetus	ite locating the pos	ition of the c	orner:		•
Placed standard mobox over monument. \$42°E 31.59' set T N48°W 97.48' set T N15°E 70.30' set T	.C. Remon. ta .C. Remon. ta .C. Remon. ta .C. Remon. ta rner conc. bu rner conc. bu	ed Corner G-  ag & spike i  ag & spike i  ag & spike i  ag & spike i  ridge deck (  ridge deck (  ridge deck (	n SW face n S. face n W. face n W. face (36.5' x 20 (36.5' x 20 alt pavement	8E. P P. Pol P. Pol P. Pol 24" Ma ''). '').	laced me.e.e.	dge)	المراجعة عالم
Surveyor's Michigan License No	23503	1.7.7			\ SU.	,	) Value
	APPROVED	12 /1 /6, FORN	APPROVED BY MICHIG	AN STATE BOAR	2050 p of Profession	13 HAL SURVEYORS REVISET	5, JAN. 28, 1971 D MAY 14,1975
•	0	RRB			Pagaga care	REVI	SED JAN, 1983 SED OCT, 1995

April 30, 1921 A. D. Road Plans No. 193 surveyed for Board of County Road Commissioners by B. V. Hoyt.

No mention of object found or set.

6 1/2' South of centerline. 22.4' from N. E. wing and 9.7' from S. E. wing of bridge. Drawing indicates corner is East of bridge and county drain.

1937 Witness card on file at T.C.R.C., W. E. Evans of Robt. Gage Coal Co. found old cedar post, set l 1/4" x l" steel bar 36.3' East, to NW cor. Sec. 3, T14N-R8E.

S.E. 33.35' to galv. marker in 8" Ash. S.W. 13.25' to cor. of br. rail support. N.W. 22.23' to cor. of br. rail support.

N.E. 33.02' to Tele. pole.

