SURVEY & REMONUMENTATION

JAN 1 4 1998

VAN BUREN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

Ec 20 10 Ec 14 107

| | DEC TO 10 26 MM 31 |
|---|---|
| For corners in SECTION | May On Built |
| Van Buren Located In: Bloomingdale Twp. Corner Code # H-1 | Mark a Smith |
| 1. Public Land Survey T 1 S R 14W T R T R T R T R T R 10 Section S T R S T R S T R T R T R T R T R T R T R T R T R T R | Liber 5 Page 94 816 Register of Deeds Stamp & File 27 |
| | 99 29 |
| 4. Lot No, Recorded Plat | A B C D E F G R I J KFCI |
| I, Robert E. Lemke, in a field survey on August 21, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. | 2 |
| A. Description of original monument and accessories and/or subsequent restoration: H-1 GLO H-1 Recorded Survey not set L.4,P.1 (8-23-73) Found 1-1/2" Pipe Same witnesses as Pipe is 3.5 West of NS. fence and is 10' North of fence to West and 24' East of center of NS road 26" Beech S25 E 34.05' to Nail & Tab 22" Maple N45 E 42.96 to Nail 14" Ash S85 E 34.79 to Nail 14" Ash West 2.26 to nail H-1 not shown on survey | H-1 Recorded Survey L.9,P.373 10-7-1992 Same witnesses as L.4,P.1 of Surveys. No distance shown to corne. Railfied by Peer Group in accordance with P.A. 345 of 1990 Van Buren County Surveyor Date D. R. J. 12/26/97 |
| B. Description of corner evidence found and/or method applied in restoring or reestablish | ing corner: |
| Found 1-1/4" Pipe (O.D.) per witnesses shown above. Pipe is 277.33' South of the town I section corner in any of the recorded surveys I reviewed. A 1962 survey by Don E. Allen set south of H-1. Searched for corner with similar easting on town line and found 1-1/2" pipe is 0.66' South of town line as defined by K-13 & H-13. I-13 is in Eagle Lake. | shows that Allen set a property corner 277 |
| This position not established by original government surveyors. The 1-1/2" Diameter(O.D.) evidence of the position of the corner. |) pipe is accepted as the best available |
| C. Description of monument for corner and accessories established to perpetuate locating | the position of the corner: |
| H-1 4" Harrison Marker set on town line as defined by K-13 & H-13 of Cheshire Township | (T 1 N, R14 W, Allegan County, MI). |
| H-1 is 3855.89' Westerly of K-13 (SE Corner Section 35 T1N R14W). 1-1/2" Diameter(O.D.) pipe is South 0.66ft Set PK nail and Van Buren County Witness Tag 1.2' above grade in 16"Aspen N45°E 31. Set PK nail and Van Buren County Witness Tag 1.8' above grade in S side of a 36" Maple Set PK nail and Van Buren County Witness Tag 1.5 above grade in W side of a 30"Ash S0 Set PK nail and Van Buren County Witness Tag 0.8 above grade in the south side of the ea | \$40 E 33.61ft 5 E 31.74ft |

Surveyor's Michigan License No.40160

FORM APPROVED BY MICHIGAN STATE BOARD OF

For SDI CONSULTANTS LTD.