



10/26/1926 - T. A. Smith, C.S.

Section 10

Red Book

Found Iron Pipe in center line of East and West Road.

**Witnesses:**

Pipe - 33' - South.

Steel Flag Pole - S. 60 Deg. E. - 149.5' to center line.

Near corner of armory - S. 30 Deg. E. - 197.0'.

Distance East is 1316.5' to Eighth Post and continuing East 1316.5' to Section Corner for a total of 2633.00'.

1930 to 1935 - Section 15.

Distance West 1315.9' to Eighth Post and continuing 1315.9' to Northwest Corner for a total of 2631.80'.

Distance East 1316.5' to Eighth Post and continuing East 1316.5' to Northeast Corner for a total of 2633.00'.

Distance South 1317.4' to Quarter Post and continuing South 1317.4' to Center Quarter Post for a total of 2634.80'.

Angle West to South is 90.38'.

1935 Field Note - Distance East is 1317.46' and continuing East 1317.46' for a total of 2634.92'.

1943 Field Note - Same as above.

8/11/1962 - W. Q. Smith, C.S.

"Supervisor's Plat of Irving T. Olson Industrial Subdivision" (Liber 5 - Page 74).

Shows distance West of 1315.9'.

Monument South 33'.

9/18/1969 - Michigan Department of Transportation - card.

Ackerman Plug - Aylworth Ave. and Center Street.

**Witnesses:**

S. 20 Deg. W. - Northeast Corner Cyclone Fence - 37.82'.

N. 50 Deg. W. - Southeast Corner of old store building - 89.30'.

N. 45 Deg. E. - Southeast Corner of Southwest chiseled X - 47.14'.

No Date - Tax Description Office.

Drawing shows distance West of 1315.9' to Eighth Post and continuing West 1315.9' to Section Corner for a total of 2631.80'.

Distance East of 1316.48' and continuing East 1316.08' to Southeast Corner of Section for a total of 2632.56'.

Distance South is 1317.26' to Eighth Post and continuing South 1317.26' to Quarter Post for a total of 2634.52'.

Distance North is 1315.15' and continuing North 1320.00' to Center Quarter Post for a total of 2635.15'.

5/7/1973 - G. Mitchell, R.L.S.

Section 15

Recorded Survey (Liber 4 - Page 84).

P.K. Nail in joint of Pavement.

**Witnesses:**

Power Pole - S. 10 Deg. E. - 22.40'.

Power Pole - N. 45 Deg. W. - 49.85'.

Northeast corner Fence - S. 30 Deg. W. - 37.90'.

4/16/1973 - Recordation Certificate (Liber 2 - Page 115).

P.K. Nail in joint of Pavement and witnesses the same as Recorded Survey above. Set from information on Supervisor's Plat of Irving T. Olson Industrial Subdivision.

Found Northwest Corner of Section, measured East 2631.8' P&M and North 33.00' from Iron Pipe on Quarter Line.

10/13/1977 - D. R. Gilchrist, C.S.

Section 15

Recorded Survey (Liber 7 - Page 146).

**Witnesses:**

Power Pole - S. 15 Deg. E. - 22.29'.

Power Pole - S. 20 Deg. W. - 28.56'.

Power Pole - N. 45 Deg. W. - 49.90'.

Distance East 1316.48' to Eighth Post and continuing 1316.08' to Northeast Corner of Section for a total of 2632.56'.

Distance South is 1317.26' to Eighth Post and continuing South 1317.26' to Center Quarter Post for a total of 2634.52'.

7/7/1978 - Recorded Survey (Liber 8 - Page 161).

Section 10

Shows corner and witnesses (same as above).

Distance East is 1316.48' to Eighth Post and continuing East 1316.08' to Section Corner for a total of 2632.56'.

*Liber 4 pg 331*