	Adli par	en comich vemonamencacion	i talla fala C dilli an
For comers in Arlington	F	AND CORNER RECORDATION CERTIL Filing Requirement of Act 74, Mich. P.A. Section Corner 14,15,22,23	1970
Van Buren (County)	Located in:	Corner Code #	वस्तिकार्यो है है है है है है
I. Public Land Survey	т <u>2S</u> т т	R 15W 17	
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	ST ST ST	RRatified by Peer Group in Paccordance with P.A. 345 of 1990 RVen Buren County Surveyor R	Liber 4 Page 485
Property in Sec.	S I	R	Register of Deeds Stamp & File

5/28 Gary C. Bilow In a field survey on 5/28 19 3 do hereby state that under requirements of P.A. 74, Michigen P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Burseu of Land Management or by a decree of a Court of Law and for , 19 $\frac{93}{}$ do hereby state that under that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

, Recorded Plat

4. Lot No.

5. Private Claims

recovered, found as expressed below:

	A	B	c t)	E	F C	3 P	ŧ.	Į,	J H	()	L M
1		1		F								
2	⊩	6—	 	\$—	 	<u> </u>	 - :	<u>-</u>	- :	ģ	-	ļ⊢ļ
3	┝	╁	├		-		-				- -	
4	<u> </u>	<u> </u>	 ;	₿—	\vdash	9—	<u> </u>	<u> </u> o	<u> </u> -1	1	 	2
5	┝	╀	<u> </u>	<u> </u>	 	-	<u> </u>					\vdash
6	<u> </u> -:	ί <mark>θ—</mark>	— 1	<u>'</u> —	1	6	1	 5	1	4	1	3
7	<u> </u>	ļ	<u> </u>		<u> </u>						<u> </u>	\sqcup
8	<u> </u>	9	2	<u>0</u> _	2	 1	2	2	<u>2</u>	3	_2	4_
9	_	<u> </u>	<u> </u>	_		ldash						
10	<u> </u>	 30	2	و		8	<u>2</u>	7_	<u>2</u>	6	2	5
11		 -	_			\square		\dashv				
12	ļ.	ļ 1—	3	2	3	3	3	4	3	5	3	6-
13	L	L				l						

OF MICHIG

GARY C. BILOW ROFESSIONAL SURVEYOR No.

12/20 0101 10SURVEY

A. Description of original monument and accessories and/or subsequent restoration:

Post established by U.S. Deputy Surveyor G. Harrison in 1830 - accessories: Sugar 20 S29E 6 links and Beech 18 S56W 7 links. County Surveyor W.H. Goss recorded in 1907 in the Red Book Page 23 "Stone - accessories: 10" Walnut SW 77 links." County Surveyor T.A. Smith recorded in 1927 in his field notes "Stone found-accessories: 12" Elm N43W 43.8' to center, 15" Elm S76E 22.9' to center, 18" Maple N15E 75.9' to center, and 18" Walnut S35W 51.2' to center." E. Stefan (PS #13599) recorded on a Act 132 Survey recorded in Liber 1 Page 268 "Iron-accessories: West 21.0' edge Street Sign, N35W 39.62' Nail in 10" tree, and N45E 44.6' edge Stop Sign." Alton Howard (PS #2382) in an Act 132 Survey recorded in Liber 1 Page 265 "Iron pine accessories: NAEE 206.2' Talenhore pale and Nest 21.5' Street sign." 2 Page 255 "Iron pipe-accessories: N45E 206.2' Telephone pole and West 21.5' Street sign."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found 1/4" x 1" Iron Bar over large stone and two (2) of Stefan's accessories. Distances to adjacent corners were reasonable and consistent. Accepted this Iron Bar as the best evidence of the original GLO post.

THIS GOVERNMENT MONUMENT WAS RESTORED WITH THE APPOVAL OF THE VAN BUREN COUNTY REMONUMENTATION PEER GROUP OF SURVEYORS AT A MEETING HELD OCTOBER 9, 1996, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 1/4" x 1" Iron Bar and stone with Harrison Monument on 12/18/96

	•	
West	21.0'	Street sign post
N45°W	39.35'	Nail in 10" dead Ash
S52°W	32.56'	Nail in 13" Ash
East	1'	centerline 50th Street
North	3′	centerline 36th Avenue
N35°E	66.59'	nail in 16" Maple

Signed by Surveyor's Michigan License No

PAGE 14

OFESSION December 19,1996