SURVEY & REMONUMENTATION

JAN 1 4 1998

Van Buren County Remonumentation Program

SECTION

For corners in Covert Township

Van Buren

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970
Quarter Corner 25,26

FILED

<u>Van Buren</u>	Located In:	Corner Code #			A.	
(County)			}			
1. Public Land Survey	T <u>2SR1</u> TR_ TR_	<u>7W K10 </u>	-		DEC 11	4 33 PM 97
2. Property Controlling in Section	T_R S_ T_R S_ T_R		-	1 01-0	Mark	Le Sneith
Miscellaneous Property in Sec.	S TR_		-	∠ i BER Register of		PAGE 18 Imp & File Number
4. Lot No, Record	ied Plat			A B C D	E F G	HIJKL
				2 - 6 - 5		-31-
I, Gary C. Bilow, requirements of P.A. 74, Michigar conformance with regulations and united States Department of the Inthat the corner points mentioned is Board of Land Surveyors or by recovered, found as expressed belo	n P.A. of 1970, the corner pruies therefore as required interior, Bureau of Land Man in lines 3, 4 and 5 above we a Decree of a Court of I	points mentioned in lines 1 in the current manual of sur agement or by a decree of a are in conformance with the	and 2 above were in vey instructions of the a Court of Law and /or rules of the Michigan	5	9-16-	-10 -11 -12 - -15 -14 -13 - -22 -23 -24
NOTE: Not more than 2 comers, all in the same town and range, may be recorded				9 -		
on this certificate.				10 30 29	28_	_27 <u>26</u> 25
				11		
				12 31 32	33	-34 -35 -36-
13 links. In May, 1871, Costake and witnessed an 8' corners. In March, 1937, miles north, 2625.0, south County Road Commission east end of culvert S85°E, edge of the road on a strais SCS tag in pole, S10°W, 6 East, 79.70 and a PP S30 B. Description of corner evide K10, Found a RR spike of SCS tag in pole SW from as the best available evide THIS GOVERNMENT MREMONUMENTATION ACCEPTED AS THE BE	Tamarac, SW, 13.5 lii County Surveyor TA Si 2625.0 and east 2618 found a 1-1/2" pipe w 26.13; tack &washer i ight line split of the mile 9.50. Surveyor J Kam °E, 72.28. Kamer show ence found and/or meth ver a large stone 0.8 for 1972 Road Commission ence of the position of the MONUMENT WAS RI PEER GROUP OF S	nks. In 1895, County Smith set a pipe in line vi.46. He measured a 3 vith a ½" pipe inside an n a triple cherry, N45°\ e in April, 1975. Howaner set a spike for the cows a 31 minute deflection applied in restoring coot east of centerline of n notes 0.4 foot long. It is original corner. ESTORED WITH THE SURVEYORS AT A IN	Surveyor WH Goss with the north edge of minute deflection of witnessed a tack of the witnessed a PK orner in 1983 and on at the corner. Frank Street. Kan Also found 1/2" rebate E APPROVAL Of MEETING HELD	s set a stake halfort of a ditch west. In at the corner. In and SCS washe or AW Howard four nail in N face pol- witnessed a RR to ther: her witness to pol- ar on west edge of PF THE VAN BU FEBRUARY 26	vay betwee Smith mean 1972, the r in pole, S and an iron le, East 91. die, N45°E, e east mate of road. Ac	n the section sured north half Van Buren 10°W, 71.53, rod on the west 65 and nail and 39.58; a PP ches. Found scepted RR spike
S 18° W, N 90° W, S 29° E,	or corner and accessorie, broke stone and place, proke stone and place, 79.72, spike & DNR ta, 72.34, spike & DNR ta, 12.02, ½" rebar 52.3, face of GTE tele, 71.93, spike & SCS B	ed 20" Harrison monur ag in PP tag in PP phone riser M tag in PP	Ratified by Peer Gr Cordance with P.A. 3. Yan Buren County St	oup in 45 of 1990	essed	OW SIONAL SIYOR 53
Signed by	eng C. 12	Silow	Date	November 19		elden.
Surveyor's Michigan License No	26	3453				