

JAN 17 1996

DEC 22 9 52 AM '95

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Van Buren
(County)
Antwerp Twp.

Located In:

Corner Code #

- | | | |
|-------------------------|----------------------------|------------|
| 1. Public Land Survey | T <u>3 S</u> R <u>13 W</u> | <u>G-3</u> |
| S.W. Cor. Sec. 3 | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling | S _____ T _____ R _____ | _____ |
| in Section | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous | S _____ T _____ R _____ | _____ |
| Property in Sec. | S _____ T _____ R _____ | _____ |

Mark A. Smith
VAN BUREN CO.
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, James E. Baynton, in a field survey on February 1, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. established the corner in 1829, W. Brookfield, D.S.
A.J. Teed found and used corner in 1873.
W.G. Smith relocated corner and set brass cap, no evidence of relocation procedure given.
Numerous surveys from 1956 thru 1992 used brass cap.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found brass cap from witnesses, at the direction of the Peer Group on January 25, 1995.

Ratified by Peer Group in
accordance with P.A. 345 of 1990
Van Buren County Surveyor

Date 1-25-95 J. E. Baynton

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found brass cap and stamped LS# 29239 on it. Set mon. box over corner & below surface. This position is accepted careful and faithful reestablishment of the position of the original corner.
Nail in S.W. side Power Pole N. 23° W. 165.61'
Nail in N.W. side Power Pole S. 69° W. 101.05'
N.W. Cor. foundation of house S. 24° E. 168.26'
S.W. Cor. house foundation N. 55° E. 129.44'

Signed by James E. Baynton
Surveyor's Michigan License No. 29239

Date September 21, 1995

Side 4 Pg. 341