

Dec 20 1 44 PM '99

S/4 cor., Sec. 27

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in ANTWERP TWP.
VAN BUREN

Located In:

Corner Code #

1. Public Land Survey

T 3S. R 13W. H-11

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Allen H. McMachen, in a field survey on November 27 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 10 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

- 1829 - William Brookfield, D.S., Set quarter Section post, 18" Wh. Oak N. 55° 30' W. 97 lks. (64.02'), 16" Yellow Oak S. 27° 30' E. 117 lks. (77.22')
- 1921 - W.H. Goss, C.S., Hickory - Northeast - 14 lks. (9.24').
- 1923 - T.A. Smith, C.S., Found stones OK, 10" Oak N. 30° E. 11.2' to centerline, 10" Oak N. 50° E. 9.6' to centerline, 12" Oak N. 15° W. 31.1' to centerline, Northwest corner Grapevine S. 15° W. 25.6'
- 1995 - J.C. Hunt, R.L.S., Found iron with cap No. 23513, N. 80° E. 7.32' - Nail South face 13" tree, N. 85° W. 25.70' - Nail North face 24" tree, N. 15° W. 31.04' - Nail West face 17" tree, N. 10° E. - Nail/tag West face 15" tree
- 1996 - Roger E. Stephenson, P.S., Found stones - set concrete monuments, Rose Meadow Sub. L. 8, Pg. 111, N. 10° W. - 2" Oak - 1.2', N. 45° E. 12" Oak 7.4', S. 45° W. 10" Oak 19.4'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found concrete plat monument per (2) 1996 witnesses and (1) 1995 witness. Found remnants of old East and West fence through trees 2' South. Found plat monument was ratified by the Van Buren County Remonumentation Peer Group on November 27, 1999.

Ratified by Peer Group in
accordance with P.A. 345 of 1990
Van Buren County Surveyor

Date 12-20-99 D. R. A.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found concrete plat monument is accepted as the best available evidence of the position of the original corner. Cemented a Standard Van Buren County Remonumentation cap on existing plat monument and placed a carsonite post on the North side of capped monument, Accessories:

- Nail & Tab in North side of 24" Oak N. 85° W. 25.11'
- Nail & Tab in S.E. side of 12" Oak S. 45° W. 19.36'
- Nail & Tab in N.E. side of 5" Hickory S. 50° E. 31.34'
- Nail & Tab in South side of 14" Hickory N. 60° E. 7.36'

Signed by Allen H. McMachen

Date 12/14/99

Surveyor's Michigan License No. 16935



L. Rev 5 Pg 310