

MAY 16 1987

COMMISSION

FILED

DEC 18 9 36 AM '96

W 1/4 COR. SEC. 35

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Antwerp Township
Van Buren
(County)

Located In:

Corner Code #

Mark A Smith
VAN BUREN CO.
REGISTERED PROFESSIONAL SURVEYOR

7.00

| | | | | | |
|------------------------------------|---|-----|---|------|------|
| 1. Public Land Survey | T | 3S. | R | 13W. | I-12 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | T | R | | |
| | S | T | R | | |
| 3. Miscellaneous | S | T | R | | |
| Property in Section | S | T | R | | |

LIBER 4 PAGE 463

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

6. IWM Job No. 2680

I, Allen H. McMachen, in a field survey on October 3, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

| A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | |
| 4 | 7 | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | |
| 6 | 18 | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | |
| 8 | 19 | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | |
| 10 | 30 | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | |
| 12 | 31 | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

1829 - William Brookfield, D.S., 20" Wh. Oak N. 47° 15' E. 12 lks.
12" Wh. Oak N. 55° W. 40 lks.
1867 - C.D. Lawton, C.S. "Found both witness - Put in stake"
1900+ - W.H. Goss, C.S., Long stone on end, 14" Hickory S.E. 49.5', Spruce East 0.45'
1923 - T.A. Smith, C.S. "Found stone - cut "X" in top of stone", 3" Basswood N. 40° E. 20.8' to centerline, 4" Oak N. 10° E. 75.5' to centerline
1950 - T.A. Smith, C.S. Gone - Road cut through hill

1957 - T.A. Smith, C.S. Found iron rod
1971 - A.H. McMachen, R.L.S. Found 3/4" iron rod, Stone S. 80° W. 36.39', Iron rod East 33.00', 3' E. of centerline, Meas. North 2642.64' to NW cor., Meas. South 2639.16' to SW corner Meas. East 2621.05' to cen. 1/4 cor., Meas. South 1320.01' to 1/8 corner
1973 - W.Q. Smith, C.S. Found 1/4 post, Meas. South 1319.62' to 1/8 cor. & continued South 1318.30' to SW corner
1973 - E.R. Stefan, R.L.S. 3/4" iron Meas. North 2642.16' to NW corner Meas. East 2621.4' to cen. 1/4 cor.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron rod (smooth) in mon. box, measured North 2641.37' to Northwest corner. Measured from 1/2" iron South 1319.60' to fd. 1/8 corner and continued South 1318.16' to Southwest corner (total 2637.76'). Removed iron and excavated to a depth of 4' and found no additional marker. 1/2" iron was rafted by the Van Buren County Remonumentation Peer Group on March 27, 1996 and is accepted as the best available evidence of the position of the original corner.

Ratified by Peer Group in accordance with P.A. 345 of 1990
Van Buren County Surveyor

Date 12/18/96 D.R.A.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed standard Van Buren County Remonumentation monument at position of found iron, Accessories:

- "PK" Nail in 8" Cottonwood N. 05° E. 198.51'
- "PK" Nail in 6" Maple S. 60° E. 28.06'
- "PK" Nail in 8" Poplar S. 75° W. 42.64'
- "PK" Nail in 6" Hickory N. 10° W. 131.59'



Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 10/25/96