98-18511 G9R4-14.tff

VAN BUREN COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE DEC 7 | 37 PM '98

	Filing Requiremen	t of Act 74, Mich. P.A. 197	70
For corners in Decatur Twp.		ĺ	Mark a Smith
Van Buren (County)	Located In:	Corner Code ##	YAN BURENCO.
			in dispersion on success
 Public Land Survey 	10	G-9	
SW corner Sec. 22	TR		
	τR		
2. Property Controlling S	TR		
	T R		
	I RSURV	EV & B	Register of Deeds Stamp & File Number
Property in Sec. S	T	ENTATION -	
4. Lot No, Recor	152 (2)	1 1999	A B C D E F G H I J K L N
5. Private Claims	JAN 4.	= 1999	
	do New do you	24 do h .	3
	SECT	TON	4 7 8 9 10 11 12
John C. Hunt, P.S. , in	a field survey onFeb. 2	, 1998	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 a 19 20 21 22 23 24			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			
Court of Law; established, re-est expressed below:	tablished, monumented, re-monum	renied, recovered, tourio as	10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11
on this certificate.			12 31 32 33 34 35 36
,			13
A. Description of original monument and accessories and/or subsequent restoration:			
N60°45'E 15.18'; 10" tam Sec. 27, Bk.2 p58: Stone 11/18/1907 CB Goss DCS: post & cont. E 1324.29' dist. E. is 2643.2' & on of travel; dist. W is 13 Drain Off.: Sec. 27 Isha Notes fd. iron strap: S% 1322.34' to S% post for B. Description of corner evide G-9 Southwest corner of Sections 21, 22, 27, & 2 Corner evidence found: F and set Harrison marker centerline of drainage d THIS GOVERNMENT MONUMENT OF SURVEYORS AT A MEETIN	Tarack N72°W 19.14'. Dist. Dist. E is 5246.34'. 19 Sec. 27 Bk. 7 p104: Fd. s to % post, total 2648.58' 8/7/1946 in Sec. 28 fd. 23.5' to 1/8th post & com m Drain ends 660' E. & 16 (post & center, dug out t total of 2644.68'. Ince found and/or method applie Section 22, T4S-R14W, Dec 8: Cound iron strap 1/4" x 3/ in mon. box over stone.	E is 5318.28' & W is 100+/- WH Goss CS: Sec. take & stone, no wit.; .4/8/1929 TA Smith CS pipe & wit.: 10" elm Nit. W 1323.5' to ½ post .5' S. of NW cor. of second place new culverts, of the restoring or reestablishing atur Twp., Van Buren Co. 4" x 13" over 1½" iron Corner in centerline of AL OF THE VAN BUREN CO. 8, AND IS ACCEPTED AS 100.	o., MI., corner common to pipe over stone. Removed irons f road East & West & 3' East of UNTY REMONUMENTATION PEER GROUP
G-9 Harrison Marker in m S36°E 42.72' Set mag nai N25°W 46.90' Set mag nai S12°W 31.55' Set PK nail S64°E 81.52' Set PK nail	l in W. face of pole. l & washer in E. face of & washer in W. face of 1 & washer in N. face of 4	pole. 3" dia. tree. " dia. pine tree. fiffed by Peer Group in lance with P.A. 345 of 1998 Buren County Surveyor R.A. 12-7-98	JOHN C. HUNT PROFESSIONAL SURVEYOR NO. 23513 POFESSIONAL PROFESSIONAL PROFESSIO
Signed by	Henry ps	Date	Oct. 21, 1998
Surveyor's Michigan License No	023513	FORM A	APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19
		2905 12/07 0104 1	REVISED MAY 14, 19 REVISED JAM., 19 OSLIKUEY 700

L. bev 5 pg 160