

\$ 4.00 REMONUMENTATION

\$ 7.00 DEED

26 DEC 95 3:23 P.M.

RECEI

RECORDED

FOREST E. YOUNGBLOOD, REGISTER
WAYNE COUNTY, MI

EDS

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

WAYNE
(County)

Located In:
PLYMOUTH TWP

Corner Code #

1. Public Land Survey

T 1 S R 8 E

K-12

T R

T R

T R

S T R

S T R

S T R

S T R

2. Property controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 12-13-95
WAYNE COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

COMMISSION

REVISITED 12-12-95

JANUARY 30, 19 95

I, PAUL V. SCHWIMMER, in a field survey on
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

ORIG. GOVERNMENT NOTES 1815, WITNESSED
BY BALESS JIMMINGS - SET POST (1)
SUGAR MAPLE 5° N 74 1/2° W 22 LINKS (2)
IRONWOOD 6° S 58 1/2° E 5 LINKS (3)

WAYNE CO. BUREAU OF TAXATION (1930'S)
IRON (4)

N.W. 69.10' 20° DAK (5)
S.E. 57.74' 15° HICKORY (6)

S.W. 127.50' 10° ASH (7)

N.W. 47.75' CROSS IN CULVERT HEADWALL (8)
N.W. 47.50' CROSS IN CULVERT HEADWALL (9)

ACT 74 SURVEY L18086 PA444
FND CHISLED "X" IN PAVEMENT REPLACED WITH
3/4" PIPE IN MONUMENT BOX
BY N.C. JONES IN 1972 (4a)
N 60° E 83.88' TELE POLE (10)
S 40° E 70.71' 9° ASH (11)
SOUTH 76.80' 8° ASH (12)
N 15° W 69.33' 27° DAK (13)

ACT 132 SURVEY L18086 PA444
FND MONUMENT (NO DESCRIPTION) BY
ROBERT PATTERSON RLS# 17631 IN 1978 (4a)

B. Description of corner evidence and/or method applied in restoring or reestablishing corner:

K-12
THE FOLLOWING WITNESS TIES TO THE CORNER WERE RECOVERED OR ESTABLISHED:
FOUND 3/4" IRON PIPE IN MONUMENT BOX IN CENTERLINE OF ANN ARBOR ROAD (4a)
N 15° W 69.33' 27° DAK (13)
SOUTH 76.71' NAIL IN E. SIDE 18° ASH, NAIL OVERGROWN W/ BARK (12)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-12
FOUND 3/4" IRON PIPE IN MONUMENT BOX IN CENTERLINE OF ANN ARBOR ROAD
N 20° W 69.48' NAIL IN W. SIDE 42° DAK, NAIL OVERGROWN WITH BARK (14)
N 20° W 69.40' NAIL IN W. SIDE 42° DAK, NAIL OVERGROWN WITH BARK (15)
N 50° E 80.46' P.K. NAIL W/ PLASTIC TAG (TAG UNREADABLE) (16)
N 15° W 69.33' 27° DAK (13)
S 02° E 51.33' FOUND 16d NAIL W/ FLAGGING ON E. SIDE POWER POLE (17)
S 02° E 51.80' NAIL AND PLASTIC TAG "GLA 28400" IN W. SIDE POWER POLE (18)
SOUTH 76.71' NAIL IN E. SIDE 18° ASH, NAIL OVERGROWN W/ BARK (12)
DIST TO N.W. CORNER SECTION 36 2653.61' MEAS & 2653.18' REC IN 1930'S
DIST TO S.W. CORNER SECTION 36 2638.46' MEAS & 2638.25' REC IN 1930'S

WAYNE COUNTY REMONUMENTATION
TAGS WERE PUT ON ALL APPROPRIATE
WITNESSES AND REMONUMENTATION
DISKS WERE PLACED ON THE
PHYSICAL MONUMENT

THE SELECTED LOCATION IS ACCEPTED BY THE CONTRACTOR AND IS GENERALLY ACCEPTED BY PROFESSIONAL
SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by

Paul V. Schwimmer

Date 12-11-95

Surveyor's Michigan License No. 24618

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1978
REMOVED JAN. 1983

LIBER 28482 PAGE 686

95274740

