

DEC 29 1998

FILE DO NOT MAIL

SURVEY &
REMONUMENTATION

MAR 02 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 SECTION

For corners in

WAYNE

(County)

Located In: NORTHVILLE TWP. Corner Code #

1. Public Land Survey T 1 S R 8 E L-3
T R
T R
T R
2. Property controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 12-8-98
WAYNE COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

I, CHRISTOPHER S. LAMUS, in a field survey on FEBRUARY 16, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

ORIG. GOVERNMENT NOTES 1815
BY JOSEPH WAMPLER -- SET POST
7" IRON N.17°E. 26 LINKS (1)
14" LYNN N.17°E. 46 LINKS (2)

NO G.L.O. WITNESSES REMAIN

\$7.00 DEED

RECORDED

FOREST E. YOUNGLOOD, REGISTER OF DEEDS
WAYNE COUNTY, MI

Receipt #101861

\$4.00 REMONUMENTATION

B. Description of corner evidence and/or method applied in restoring or reestablishing corner:

WAYNE CO. ROAD COMMISSION 1974
(L-3) FOUND MONUMENT IN MON. BOX
N.WEST 54.70' TO 18" MAPLE (1)
N.EAST 55.78' TO 16" MAPLE (2)
S.EAST 31.14' TO 17" ELM (3) GONE
S.WEST 31.28' TO MBT POLE (4) GONE

WAYNE CO. ROAD COMMISSION 1970
(L-3) FOUND MONUMENT IN MON. BOX
N.WEST 54.64' TO 17" MAPLE (1)
N.EAST 56.35' TO 14" MAPLE (2)
S.EAST 31.20' TO 18" ELM (3) GONE
S.WEST 31.35' TO MBT POLE (4) GONE

PUBLIC ACT 74 L.C.R.C. L.27276 P.696
(L-3) FOUND IRON ROD IN MON. BOX
N.53°W 81.90' P.K. S.FACE 20" MAPLE (5)
N.17°W 53.51' P.K. E.FACE 24" MAPLE (1)
N.19°E 54.60' P.K. W.FACE 20" MAPLE (2)
S.15°W 45.03' P.K. N.E. FACE OF 10" ASH (6)

PUBLIC ACT 74 L.C.R.C. L.24088 P.804
(L-3) FOUND IRON IN MON. BOX

DISTANCE TO K-3 2641.25' (M) RECORDED AS 2641.43' BY WAYNE COUNTY BUREAU OF TAXATION.
DISTANCE TO M-3 2768.08' (M) RECORDED AS 2768.16' AS SHOWN IN SITE SURVEY PLAN AS RECORDED IN L.27004, P.392.
DISTANCE TO M-3 2768.08' (M) RECORDED AS 2768.00' BY WAYNE COUNTY BUREAU OF TAXATION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-3
5/8" IRON ROD IN MON. BOX.
SET BRASS W.C. REMON WASHER AND SURVEYOR'S CAP #41914 OVER 5/8" IRON ROD.
MONUMENT IS LOCATED IN PAVEMENT IN THE SEVEN MILE ROAD RIGHT-OF-WAY.

N.20°W 54.33' SET W.C. REMON WASHER E. FACE 24" MAPLE (1)
N.15°E 55.55' SET W.C. REMON WASHER W.FACE 22" MAPLE (2)
N.56°W 82.34' SET W.C. REMON WASHER S.FACE 24" MAPLE (5)
S.13°W 44.14' SET W.C. REMON WASHER NE FACE 10" ASH (6)
N.50°E 93.81' SET W.C. REMON WASHER IN MW FACE 24" MAPLE (7)
S.59°E 67.65' SET W.C. REMON WASHER IN NE.FACE 15" ELM (8)

THE SELECTED LOCATION IS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE

Signed by Christopher S. Lamus

Date 12/29/98

Surveyor's Michigan License No. 41914

R LCR 7 4R 1PG U. DPJ

