

DEC 29 1998

FILE DO NOT MAIL

SURVEY &
REMONUMENTATION

MAR 02 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

\$10.00 REED

For corners in

Wayne, Van Buren Twp.
(County)

Located in:

Corner Code #

1. Public Land Survey

T 3S. R 8E.

I-6

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

\$4.00 REMONUMENTATION

RECORDED

FOREST E. YOUNGBLOOD, REGISTER OF DEEDS
WAYNE COUNTY, MI

Receipt #101860

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 12-16-98
WAYNE COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, William L. Roskelly, in a field survey on Nov 28, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4		3		2		1
3													
4	7			8			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-6 West corner section 14, T.3 S., R.8 E., Van Buren Township

G.L.O. (1830's) Joseph Fletcher set corner post, witnesses: B. 026 S36 W12 (gone), Do 28N44 E25 (gone) W.P.A. (1930's) stone, witnesses: NW 29.48' 30" poplar (gone), E 21.53' 8" bldg cor. (gone), SW 53.46' 24" Elm (gone), NW 56.39' Tel. pole (gone), NW 82.21' 6" Elm (gone), WCRC 6/2/70 E. Johns iron, witnesses: NW 22.07' nail 26" Catalpa (gone), SW 35.20' nail in 24" Catalpa (gone), SW 27.37' nail in 24" Catalpa (M=27.30'), Due West 45.24' bldg. #10400 corner (gone), WCRC 1/27/87 found 1/2" iron pipe down 3" from gravel road, witnesses: NW 117.65' NE corner frame house (gone), SW 36.18' PK nail brass tag 29" tree (M=36.32'), SW 28.58' PK nail 26" tree (gone), SW 38.00' PK nail in brass tag fence post (gone), SW 88.54' SE corner frame house (M=88.54'), 4/23/97 LCRC L. 29601. P. 3664 William G. Carlson found an iron pipe, witnesses: San. MII, N.15°E., 92.52' (M=92.31'), PK nail WCRC tag NE side 30" tree N.80°W., 22.91' (M=22.56'), found capped pipe, (over)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-6 West corner section 14, T.3 S., R.8 E., Van Buren Township

Found an iron pipe 1' below gravel surface of Morton Taylor Road (gravel).

Verified corner location by comparing W.P.A. data with field measurements.

I-6 to I-5 Record = 2684.45' Measured = 2683.28' I-6 to I-7 Record = 2673.65' Measured = 2674.31'

Angle line I-6 & I-5 to I-6 & I-7 Record = 179°-27'-40" Measured = 179°-27'-59"

WCRC 6/2/70 E. Johns SW 27.37' nail in 24" Catalpa (M=27.37'), WCRC 1/27/87 SW 36.18' PK nail brass tag 29" tree (M=36.32'), SW 88.54' SE corner frame house (M=88.54'), 4/23/97 LCRC L. 29601. P. 3664 William G. Carlson San. MII, N.15°E., 92.52' (M=92.31'), PK nail NE side 30" tree N.80°W., 22.91' (M=22.56'), found capped iron S.55°W., 37.87' (M=37.84'), PK nail WCRC tag E. side 24" tree, S.40°W., 36.20' (M=36.32').

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-6 West corner section 14, T.3 S., R.8 E., Van Buren Township

Found an iron pipe 1' below gravel surface of Morton Taylor Road (gravel). The selected location is accepted by the contractor and is generally accepted by professional surveyors as the best available evidence of the position of the corner. WITNESSES: Found center San. MII top N.12°-34'-08"E. 92.31', found PK nail and tag #17618 S. face 12" Ash S.87°-32'-34"E. 55.08', set steel bar and cap #10705 S.44°-53'-55"E. 49.48', found PK nail and WCRC tag E. face 30" Catalpa S.33°-21'-57"W. 36.32', found nail and MSHD tag N. face 30" Catalpa S.50°-12'-40"W. 27.30', found iron pipe S.60°-44'-03"W. 37.84', found SE corner brick house #10420 Morton Taylor S.87°-15'-17"W. 88.38', found PK nail WCRC tag N. face 32" Catalpa N.63°-49'-27"W. 22.56', Set PK nail and Wayne County Remonumentation brass marker and B&S #10705 in iron pipe.

Signed by

William L. Roskelly

Date DEC 28, 1998

Surveyor's Michigan License No. 10705

R LCR 10 +R 2PG U. D.P.J.



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 20, 1971
REVISED MAY 14, 1975
REVISED JAN. 1985
REVISED OCT. 1985

SURVEY &
REMONUMENTATION

MAR 02 1999

SECTION

1-6) West corner section 14, T.3 S., R.8 E., Van Buren Township (continued from part "a" side 1)
S.55°W., 37.87' (M=37.84'), PK nail WCRC tag E. side 24" tree, S.40°W., 36.20' (M=36.32').