

SURVEY &  
REMONUMENTATION

RC 1123

DEC 02 1993

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LI 26951 PA 754

For corner in COMMISSION

Wayne

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 4S R 9E

K-2

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 10-28-93 TCA  
WAYNE COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Bruce Antcliff, in a field survey on August 18, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-Post  
WPA (1930's) - Iron  
LCRC (1976)-Steel Rod in Mon. Box (L19472, P 770)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

5/8" Rod In Mon. Box; Measured to SW S.1-Checks well  
w/WPA Surveys.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 4" x 36" Con. Monument w/Wayne County Remonumentation Marker and Cap #25826

Witnesses

Top Center Fire Hyd., N20W, 165.95'  
Nail & WCRC Tag S. Side MBT Pole, West, 33.58'  
Center of Lock Tab Sun Pipeline MH, S45E, 57.95'  
SW Corner Hse. #18043, N70E, 118.29'

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Signed by

Bruce Antcliff

Date 11-10-93

Surveyor's Michigan License No.

25826



NOV 10 PM 2:27  
FOREST  
RECORDS  
CLERK  
MICHIGAN