SUMVEY & REMONUMENTATION

MAY 1 0 2000

RECFIVED

1999 DEC -3 PM 12: 44

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Linka Loughmiller

For corners in				WEXFORD & COUNTY, MI REGISTER OF SEFOS
WEXFO		Located In:	Corner Code #	"REALEST OF TO SET US
1. Public Lar	d Survey	T 21N R 9W T R T R	J-7	
2. Property (TR		
in Section 3. Miscellane Property i	ous S_	T R		Register of Deeds Stamp & File Number
	, Recor aims	ded Plat		
do hereby state mentioned in lin required in the Interior, Bureau mentioned in lin Land Surveyors	that under requiremes 1 and 2 above we current manual of sign of Land Management as 3, 4 and 5 above were the second seco	ere in conformance with re urvey instructions of the U or by a decree of a Court of were in conformance with the a Court of Law; establishe	n JULY 19 , 1999, P.A. of 1970, the corner points gulations and rules therefore as nited States Department of the Law and/or that the corner points he rules of the Michigan Board of d, re-established, monumented,	A B C D E F G H I J K L M 2 6 5 4 32 1 3
	nore than 2 corners ertificate.	, all in the same town ar	d range, may be recorded on	8 . 19
A. Description	in of original monu	ment and accessories an	d/or subsequent restoration:	
1883 A 1888 F 7 V 1896 A 1902 D 1965 C 1996 F 6	L. J. TEED SURVEY IN ULLER SURVEY IN TESTIMONY OF PEI VITNESSED TREE. L. J. TEED SURVEY CO. RD. COMM. WE HILLIP D. CASE PEI TETACEMENT OF CORS. AND ON RETOW OF MAPLES FOR WALLES FOR WALLES FOR S. AND ON RETOW OF MAPLES FOR S. WALLES FOR S. AND ON RETOW OF MAPLES FOR S. WALLES FOR S	IN SECTION 23 STAKE SECTION 14 FD. NO STASONS WHO HAD OFTE W. ELM S18W 17L IN SECTION 14 NO WITH BOOK 1½" PIPE, 126#30079 L.C.R.C. RECOUTEED SURVEY OF 1896 FRACED N-S ½ LINE. COUNNING EAST AND WEST.	N SEEN IT. THE STAKE WAS S TAKE UNDER CROSS-WAY FRO 2" HEMLOCK S80°E 75.00', 6 PRDED L.4, P.406 SET ½" DIA . ¼ COR WAS PLACED AT PROPERTY OF A DR FALLS IN LINE WITH AN OU ST ALONG THE SOUTH SIDE O	
B. Description	on of corner eviden	ce found and/or method	applied in restoring or reestabl	ishing corner:
NORTH	I. REPLACED WI		TH BRASS CAP, THIS CORI	46 ROAD AND IN LINE WITH FENCE ROV NER IS ACCEPTED AS THE BEST AVAILABL
C. Description	of monument for	corner and accessories e	stablished to perpetuate locatir	ng the position of the corner:
5/8"X3 NORTH N4°E S27°E	16" IRON & BRAS 1 CORNER FENC 12" TWIN WIL	TO SECTIONS 14 & : SS CAP STAMPED: 19 E POST 38.12' LOW 54.17' 75.07' 65.56'	Peer Group Reviewed and Applicate: 12 Nov 99 Richard D. Wilcox, Wexford County	OF MICALO CRAIG J. PULLEN PROFESSIONAL SURVEYOR No. 39095
1		A		AND DESCRIPTION OF THE PARTY OF

Signed by <u>Errory</u> & <u>Pallis</u> Surveyor's Michigan License No. 05 PA(IF 197 HEED

39095

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

November 3, 1999