

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>22</u> N. <u>0.</u> R. <u>9</u> W.		<u>G-3; I-3; H-3; I-4</u>
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. _____ S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 3, 19 86, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued):

H-3			I-4		
Fd. Dept. Mon.; added cedar post			Fd. Dept. Mon.; added cedar post		
10" Red Pine	S25°E	4.8'	12" Black Cherry	N20°E	48.8'
8" Red Pine	S55°W	18.3'	8" Red Pine	N80°E	68.2'
8" Red Pine	N40°W	20.5'	10" Red Pine (clp 2)	S70°E	65.0'
8" Red Pine	N15°E	10.3'	26" Yellow Pine stp	S15°W	86.3'

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- G-3 - Previous Dept. corner-1958 - (1" pipe with 4" brass cap). See 1958 Dept. of Conservation Land Corner Record by Ken Ostling for details of restoration.
 - I-3 - Previous Dept. Cor. of Record (KJO-1958). For details on corner see KJO 1958 Conservation Dept. corner record.
 - H-3 - Previous Dept. Cor. of Record (KJO-1958). KJO fd. 1901 D.E. Teed stk. point & two Teed N.B.T.'s; Teed had Govt. B.T.s.
 - I-4 - Previous Dept. Cor. of Record (KJO-1958). For details on corner see KJO 1958 Conservation Dept. corner record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-3			I-3		
Fd. Dept. Mon.; added cedar post			Fd. Dept. Mon. added; cedar post		
24" White Pine stp	N50°W	17.8'	4" Red Oak	N60°W	20.4'
17" White Pine stp	N70°E	41.7'	4" Red Oak	N50°E	8.0'
5" Red Pine	S30°W	45.9'	12" White Birch (clp 4)	S85°E	33.4'
4" Red Pine	S65°W	26.3'	32" Maple (clp)	S45°W	18.0'
Fd steel fn post	N60°E	32.8'	Ctr trail	Due S	28'
Ctr road	Due S	190' ± 5'			

SIGNED BY Carl F. Roser 01-24-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

WEXFORD COUNTY