

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>23</u> N. <u>12</u> R. <u>12</u> W.	A-7; A-8; A-9
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Dec. 20, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-7 Recovered NW Cor. of S-19, 23-12, as recovered by Consumer's Power Co. survey in 1963 (now a Wex. Co. Std. Mon. which fits two C.P.C. Wits.*).
- A-8 Recovered 4"x6"- "Sq. Conc. Ref. Mon." - as recovered by Consumers Power Co. in 1963 survey. Ref. Mon. is on West Line of Sec. 19, 23-12, & is S00°18' 09" W of 1/4 position (which falls in Hodenpyl Pond), 100.00 ft.
- A-9 Recovered Sq. Conc. Mon., SW Cor. of S-19, 23-12, as recovered by Consumers Power Co. survey in 1963; on west slope of earth dam (Hodenpyl Dam backwater).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7

Fd. Wexford Co. Mount & added
Ced. Post w/loc. tag
10" Maple S40°W 3.41
*15" Tw. Maple S85°W 12.94
*Maple Stp. S06°E 16.1
6" Maple S09°W 16.98
Trail in N-S Power
Line Due E. 125+

A-8

1/4 Cor. in Pond - Not located
Wit. to "Sq. Conc. Ref. Mon."
3" Map. N66°W 6.43
5" Map. Due S. 24.14
7" Map. S28°E 24.43
Set Ced. Post W/Loc. Tag a-
long side "Sq. Conc. Ref. Mon."
Comp. 1/4 Cor.
Position N00°18'09"E 100.00'

A-9

Fd. Large Sq. Conc. Mon.
1'x1', w/2" pipe, 2' above
ground & set ced. post
w/loc. tag.
No wit. available. Dyke
wall is due E. 44'+

SIGNED BY Carl F. Roser 12-28-78 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SPRINGVILLE TOWNSHIP
WEXFORD COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____