

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 24 N.R. 10 W.


Wexford COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 33 - 34

CORNER MONUMENT Drove 1" x 24" 1 pipe below road surface

DATE MONUMENT PLACED AND WITNESSED May 1, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" Cedar N 50 E 66.0'

6" Cedar S 40 E 57.4'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established while making a subdivision survey of Section 33. Could find no previously established corner, so accepted old E - W fence lines as best available evidence of proper location for corner. Set on line between Section corners. Road reconstruction has obliterated evidence of corner.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostberg DATE June 24, 1963
REGISTERED LAND SURVEYOR #10708