LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

1. PUBLIC LAND SURVEY		IN -:	CORNER CODE NUN		
	T. <u>24</u>	N. 10 V.	G-7; G-8; G-9		
2. PROPERTY CONTROLL- ING IN SECTION——	,T	N. E. W.			
3. MISCELLANEOUS PROPERTY IN SECTION					
4. LOT NO , REC	ORDED PLAT				
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAN	P AND
T Carl F. Roser		do hereby c	ertify that under require	ements of P.A. 74, Michigan P.A.	of 1970,
the corner points mentioned in large-established, monumented, reand rules therefore as required in Bureau of Land Management or and 5 above were, in a field surv	ines 1 and 2 a monumented, in the current by a decree of ey on	above were, in a recovered or re manual of surve of a court of law	field survey on Aug estored as expressed be ey instructions of the U Furthermore, that the 19, found, recove	gust 18, 1978, est clow and in conformance with re United States Department of the se corner points mentioned in 1i cred, restored, established or re-est of Registration for Land Surveyors	ablished, gulations Interior, nes 3, 4 tablished
A. Description of original monu	ument and acc	essories and/or	subsequent restoration:		
•• .					
B. Description of corner eviden- Found 1" pipe in cen	ce found and, iter of E-	or method appl W gravel ro	ied in restoring or re-es ad. Corner fits	stablishing corner: county road commission	witness
p 41 ti 000	mi di stant	3 12	a hatwaan faund	section corners to N &	~
Drove 1%"x20" rod eq	101025 00	and on lin	e between round	section corners to a q	.
	er over st	rong magnet		center N-S blacktop co	
Found nail and washe road per county road	er over st d witnesse	rong magnet	ic attraction in	center N-S blacktop co	
Found nail and washe road per county road C. Description of monument for	er over st d witnesse	rong magnet	ic attraction in	center N-S blacktop cor	
Found nail and washe road per county road C. Description of monument for G-7	er over st d witnesse	rong magnet	ic attraction in lished to perpetuate loca G-8	center N-S blacktop corating the position of the corner:	unty
Found nail and washe road per county road C. Description of monument for G-7 pund 1" pipe E cor. of brick house N18	er over st d witnesse or corner and a	rong magnet accessories estable Drove 14"x 5" R. Pine	ic attraction in lished to perpetuate loca G-8 20" Rod S72°E 61.0	ating the position of the corner: G-9 Found nail and wash 0 4" Elm N250W	er 45.00
Found nail and washed road per county road C. Description of monument for G-7 ound 1" pipe E cor. of brick house N18 W cor. of brick house N21	er over st d witnesse or corner and a	rong magnet accessories estable Drove 14"x 5" R. Pine 4" Twn.Map	ic attraction in lished to perpetuate loca G-8 20" Rod S72°E 61.0 1e S45°E 61.7	ating the position of the corner: G-9 Found nail and wash 0 4" Elm N250W 5 NW cor. of house S4	er 45.00 8 ⁰ E 163.
Found nail and washed road per county road C. Description of monument for G-7 ound 1" pipe E cor. of brick house N18 W cor. of brick house N21 Waple S540W	er over st d witnesse or corner and a 8°E 47.8 1°W 61.3 70.25	rong magnet accessories estab Drove 1¼"x 5" R. Pine 4" Twn.Map 9" B.Cherr	ic attraction in lished to perpetuate loca G-8 20" Rod S72 ⁰ E 61.0 1e S45 ⁰ E 61.7 y cluster	ating the position of the corner: G-9 Found nail and wash 0 4" Elm N25 ^O W 5 NW cor. of house S4 4" J. Pine S53 ^O W	er 45.00 8 ⁰ E 163. 58.36
Found nail and washed road per county road. C. Description of monument for G-7. Sound 1" pipe E cor. of brick house N18. W cor. of brick house N21. " Maple S54 ^O W. " W. Pine S62 ^O E 1. et cedar post w/loc. tag.	er over st d witnesse or corner and a 8°E 47.8 1°W 61.3 70.25 151.45	prong magnet. accessories estable Drove 14"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of	ic attraction in Shed to perpetuate local G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd	center N-S blacktop corating the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E . on ctr. co. rd. N-S	er 45.00 8 ⁰ E 163. 58.36
Found nail and washed road per county road C. Description of monument for G-7 ound 1" pipe E cor. of brick house N18 W cor. of brick house N21 Waple S540W	er over st d witnesse or corner and a 8°E 47.8 1°W 61.3 70.25 151.45	Drove 14"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar	ic attraction in lished to perpetuate loca G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag	center N-S blacktop containing the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E 0 on ctr. co. rd. N-S	er 45.00 8 ⁰ E 163.
Found nail and washed road per county road. C. Description of monument for G-7. Sound 1" pipe. E cor. of brick house N18. W cor. of brick house N21. Maple S540W W. Pine S620E et cedar post w/loc. tag. Due S	8°E 47.8 1°W 61.3 70.25 151.45	Drove 14"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar	ic attraction in lished to perpetuate loca G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag	center N-S blacktop containing the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E 0 on ctr. co. rd. N-S	er 45.00 8 ⁰ E 163.
Found nail and washed road per county road. C. Description of monument for G-7. Sound 1" pipe. E cor. of brick house N18. W cor. of brick house N21. Maple S540W W. Pine S620E et cedar post w/loc. tag. Due S	8°E 47.8 1°W 61.3 70.25 151.45	Drove 14"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar	ic attraction in lished to perpetuate loca G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag	center N-S blacktop containing the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E 0 on ctr. co. rd. N-S	er 45.00 8 ⁰ E 163.0 58.36
Found nail and washed road per county road. C. Description of monument for G-7. Cound 1" pipe E cor. of brick house N18. W cor. of brick house N21. Maple S54°W W. Pine S62°E et cedar post w/loc. tag Due S SIGNED BY	8°E 47.8 1°W 61.3 70.25 151.45	Drove 14"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar	ic attraction in G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag Due E 33.0	center N-S blacktop containing the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E 0 on ctr. co. rd. N-S	er 45.00 8 ⁰ E 163.0 58.36
Found nail and washed road per county road. C. Description of monument for G-7. Sound 1" pipe E cor. of brick house N18. W cor. of brick house N21. Maple S54°W W. Pine S62°E et cedar post w/loc. tag Due S SIGNED BY SURVEYOR'S MICHIGAN RECEPTOR STATE AND UNITED STATE	er over stand and an analysis of corner and an analysis of the standard and an analysis of the	rong magnet s. accessories estable Drove 1½"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar NO. 1202	ic attraction in G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag Due E 33.0 DATE	center N-S blacktop contains the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E 0 on ctr. co. rd. N-S CARL F. ROSE LAND 12028	er 45.00 8°E 163. 58.36 93.15 -E
Found nail and washed road per county road. C. Description of monument for G-7. Sound 1" pipe E cor. of brick house N18. W cor. of brick house N21. Maple S54°W W. Pine S62°E et cedar post w/loc. tag Due S SIGNED BY SURVEYOR'S MICHIGAN RECEPTOR STATE AND UNITED STATE	er over stand and an analysis of corner and an analysis of the standard and an analysis of the	rong magnet s. accessories estable Drove 1½"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar NO. 1202	ic attraction in G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag Due E 33.0 DATE	center N-S blacktop contains the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E 0 on ctr. co. rd. N-S CARL F. ROSE LAND 12028	er 45.00 8°E 163. 58.36 93.15
Found nail and washer road per county road C. Description of monument for G-7 ound l' pipe E cor. of brick house N18 N cor. of brick house N21 N Maple S54°W W. Pine S62°E et cedar post w/loc. tag Due S SIGNED BY SIGNED BY SIGNED BY SIGNED BY SIGNED BY	er over stand witnessed wi	Drove 14"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar	ic attraction in G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag Due E 33.0 DATE B DATE	center N-S blacktop containing the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E on ctr. co. rd. N-S CARL F. ROSE LAND SURVEY NO. 12028	er 45.00 8°E 163. 58.36 93.15 -E
Found nail and washed road per county road. C. Description of monument for G-7. Sound 1" pipe E cor. of brick house N18. W cor. of brick house N21. Maple S54°W W. Pine S62°E et cedar post w/loc. tag Due S SIGNED BY SURVEYOR'S MICHIGAN RECEPTOR STATE AND UNITED STATE	er over stand witnessed wi	Drove 14"x 5" R. Pine 4" Twn.Map 9" B.Cherr on Ctr. of Set cedar	ic attraction in G-8 20" Rod S72°E 61.0 1e S45°E 61.7 y cluster S73°W 98.9 N-S b'top co.rd post w/loc. tag Due E 33.0 DATE B DATE	center N-S blacktop containing the position of the corner: G-9 Found nail and wash 0 4" Elm N25°W 5 NW cor. of house S4 4" J. Pine S53°W 0 6" R. Pine N54°E on ctr. co. rd. N-S CARL F. ROSE LAND SURVEY NO. 12028	er 45.00 8°E 163.0 58.36 93.15 -E

G-7

G-8

G-9