

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford Located In \_\_\_\_\_ Corner Code # \_\_\_\_\_  
(County)

1. Public Land Survey T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling  
in Section S 36 T 24N R 11W 11  
S 36 T 24N R 11W 15  
3. Miscellaneous  
Property in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Craig W. McVean, in a field survey on Oct. 22, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

11 - None

15 - 1973 - LCRC L. 2, p. 622 - C. F. Roser - Set 1" x 36" pipe (buried) equidistant and on line between found corners to east and west. Center E-W gravel Rd. due S. 4'.  
1) 9" Maple N63°W 68.5'; 2) 6" Maple S41°W 46.1';  
3) 10" B. Cherry S46°E 61.3'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

11 - SW 1/16 Corner Sec. 36 -  
Set 2" Alum. Cap on 5/8" x 34" long iron rebar per Standard BLM procedure. Barb wire N-S in trees is 54' West. Centerline 2-track is 37' North.

15 - W 1/16 Corner common to Sec. 36, T24N, R11W and Sec. 1, T23N, R11W - Fd. 1" I.D. iron pipe in E-W gravel road. Fits witnesses #1 & 2. #3 is gone. Corner of newer fence N & E is 29.4' North and 4.4' West. 1" iron pipe accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

11 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar  
Set Blue Carsonite Post with loc. tag 1' NW  
S63°E 3.60' to set N & T in N. side 14" S. Maple  
S43°W 18.47' to set N & T in SE side 10" S Maple  
S87°W 34.67' to set N & T in S. side 10" S. Maple  
N4°W 28.97' to set N & T in W. side 10" R. Maple

15 - 1" iron pipe  
North 33.01' to set 2" Alum. Cap on 5/8" x 34" long iron rebar on line with Blue Carsonite Post with loc. tag  
S63°E 71.97' to set N & T in N. side Tw. 15" B. Cherry  
S41°W 46.49' to set N & T in NW side 20" S. Maple (#2)  
N64°W 68.80' to set N & T in SW side 19" S. Maple (#1)

Signed by:

Craig W. McVean

Surveyor's Michigan License No.: 39088

Date:

11/14/2012

