

MAY 9 1926

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Washtenaw

(County)

Located In:

Corner Code =#

1. Public Land Survey

T 28 R 5E

L-13

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Thomas L. Sutherland in a field survey on October 6, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1815 Field Notes

Unknown

G.L.O.

Oct. 23, 1935

Grid Book

W.G.R.G.

W.J. Armstrong

#2444

1" Iron Pipe

Stones & Bricks

Found the end

of an old wood

stake and pieces

of tile &

bricks. Reset with

a 1" Iron Pipe, stones and bricks.

- 1) 14" Ironwood N47°E 22 Links
- 2) 6" Ironwood N80°W 23 Links
- 3) 2" Iron Pipe N34°E 38.6
- 4) 5" Hickory N35°E 38.8
- 5) 1" Hickory N60°E 54.8
- *6) 2" Iron Pipe S30°E 38.5
- 7) 10" Hickory S71°W 70.6
- 8) 5" Apple N05°W 51.2

(SECTION A. CONTINUED ON REVERSE SIDE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Rod in Monument Box from Remaining Witnesses

*Old Witness Found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I conclude that after careful study of the record documentation and field observations, that this corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Set W.G.R.P. Cap on 5/8" Rod in Monument Box

*6) 2" Iron Pipe S30°E 38.51

*9) Power Pole N23°E 55.32 to Tag in W. Side

*11) 12" Ash N60°E 77.27 to Tag in S.E. Side

*12) Clump 4" Thornapples N45°W 43.40 to Tag in S.W. Side

*14) 8" Ash S55°E 50.20 to Tag in S.W. Side

*15) 12" Apple SOUTH 29.89 to Tag in W. Side

Signed by

Thomas L. Sutherland

Date

December 12, 1995

Surveyor's Michigan License No.

#24620

*Old Witness Found

- Copy -

(SECTION A. CONTINUED FROM FRONT)

Aug., 1951 M.S.H.D.	Grid Book (W.G.R.C.)	Monument Box	3) 2" Iron Pipe N36°E 40.2 5) 3" Hickory N60°E 54.8 *6) 2" Iron Pipe S30°E 38.5 8) Nail in 11" Apple N05°W 51.2 *9) Power Pole N23°E 56.3 10) Telephone Pole S26°W 36.3
Nov. 18, 1963 M.S.H.D.	Sheet 76 Washtenaw County Right-of-Way Book	Unknown	None
Unknown Atwell-Hicks	Sketch of SE 1/4, Section 36	Unknown	None
July 17, 1972 Atwell-Hicks J.L. Snyder	Survey 505-4	Monument Box in Centerline of Road	None
June 17, 1981 Washtenaw Engineering T.L. Sutherland	Field Notes	Iron Bar in Monument Box	*9) Power Pole N23°E 55.32 to Nail 10) Telephone Pole S30°W 36.22 to Nail *11) 6" Ash N60°E 77.40 to Nail *12) Clump 3" Thornapple N45°W 43.73 to Nail
July 7, Washtenaw Engineering C.A. Eckfeld	Field Notes	Iron Bar in Monument Box	*9) Power Pole N23°E 55.32 to Nail *11) 10" Ash N70°E 77.23 to Nail 13) PK Nail in Old Phone Pole (Now Fence Post) N30°E 38.57 *12) Clump 3" Grab Apple N45°W 43.56 to PK *14) Clump 4" Ash S55°E 50.16 to Nail
May 10, 1990 Washtenaw Engineering H.L. O'Donnell #28419	Survey R-6104	Iron Bar in Monument Box	*9) Power Pole N23°E 55.32 to Nail 10) Utility Pole S30°W 36.22 to Nail *11) 6" Ash N60°E 77.40 to Nail *12) Clump 3" Apples N45°E 43.73 to Nail
Unknown Land Surveying consultants	Field Notes	3/4" Iron Rod in Monument Box	*15) 12" Apple SOUTH 29.63 to Nail in East Side *14) 7" Cottonwood S40°E 50.19 to Nail in SW Side *11) 13" Cottonwood N50°E 77.25 to Nail in N Side *12) 12" Thornapple N25°W 43.41 to Nail in SW side

*Old Witness Found

APPROVED

DATE 11/6/95
CO. REP. EA