

REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
WASHTENAW COUNTY, MI
FEB 18 9 02 AM '97
PEOP N. HAINES
COUNTY CLERK/REGISTER

For corners in
Washtenaw
(county)

Located In

Corner Code #

| | | | |
|---------------------------|-------------|-------------|------------|
| 1. Public Land Survey | T <u>2S</u> | R <u>7E</u> | <u>J-9</u> |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling S | T | R | |
| in Section | S <u>T</u> | R | |
| 3. Miscellaneous | S <u>T</u> | R | |
| Property in Sec. | S <u>T</u> | R | |

Liber 000001 Page 0578 *pm*
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, R.T. Tietsema, in a field survey on August 20 1996,
do hereby certify that under the requirements of P.A.74, Michigan P.A. of
1970, the corner points mentioned in lines 1 and 2 above were in
conformance with the regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of
the Interior, Bureau of Land Management of by a decree of a Court of Law
and/or that the corner points mentioned in lines 3, 4, and 5 above were in
conformance with the rules of the Michigan Board of Land Surveyors or
by a Decree of a Court of Law; established, re-established, monumented,
recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be
recorded on this certificate

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or restoration:

| | | | | | | |
|---------------------------------|--------------------|---------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------------------|----------|------------------|
| Set Corner of Sections 23 & 26. | | | | | | |
| 1819 | GLO (Wrangler) | Fld. Notes | Set Original Corner | 1) 8" Ash | S60W | 285links(188.1') |
| | | | | 2) 28" Beech | S74E | 13 links (8.58') |
| 11/23/1938 | W.J. Armstrong | Resurvey (Grid Book) | Found a stone and several pieces of brick. Set 1 1/2" by 40" Iron Pipe with Stones and Brick. | 3) 12" Apple | N25E | 65.80' |
| | | | | 4) 8" Apple | N40 1/2E | 39.40' |
| | | | | 5) 8" Walnut | N83W | 102.70' |
| | | | | 6) 10" Walnut | N78 1/2W | 60.80' |
| | | | | 7) 10" Walnut | N72W | 36.80' |
| | | | | 8) 12" Apple | N29 1/2W | 71.00' |
| | | | | 9) 6" Apple | N11W | 30.60' |
| | | | | 10) 10" Apple | N3W | 60.60' |
| 9/16/74 | Robert A. Campbell | 13028 L3PG535 Boundary W.C.R. L1492PG122 | 1 1/2" Iron Pipe at N. edge of gravel | 6) 12" Walnut | N78W | 60.20' |
| | | | | 7) 12" Walnut | N72W | 36.80' |
| | | | | 11) NE Cor. Corn Crib | W.S.W. | 157.6' |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2 "x40" pipe in the vicinity of hole surrounded by brick and stone.
7) 24" Walnut N74W 36.34'
11) NE Cor. Corn Crib S71W 157.24'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1" Iron Pipe with Remon. cap and four (4) witnesses using Campbell witnesses, described as :
7) 24" Walnut N74W 36.34' to nail & R.T.
11) NE Cor. Corn Crib S71W 157.24' to nail & R.T.
12) NW Cor. Corn Crib S74W 180.85' to nail & R.T.
13) 18" Walnut N80W 130.82' to nail & R.T.

It is our opinion that this corner represents a careful and faithful perpetuation of the position of the original corner.

Signed by R. Tietsema Date DEC 02 1996
Surveyor's Michigan License No. 20712

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 1971
REVISED MAY 14, 1976
REVISED JAN., 1983

APPROVED
DATE 11/11/96
DO. REP. EX

COPY